
Office	State of New Mexico			Form C-103 August 1, 2011
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	August 1, 2011
District II $-$ (575) 748-1283	OH CONCERNATION F		30-015-21147	
811-S. First St., Artesiä, NM 88210	OIL CONSERVATION I		5. Indicate Type of Lea	ise
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 875	05	6. State Oil & Gas Lea	and the second se
220 S. St. Francis Dr., Santa Fe, NM				
37505 SUNDRY NOTIC	ES AND REPORTS ON WELLS		7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA			State	-
DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	HON EOR PERMIT: (FORM C-101) FOR	SUCH		7
1. Type of Well: Oil Well 🛛 G			8. Well Number 2	
2. Name of Operator			9. OGRID Number	
COG Operating LLC 3. Address of Operator			10. Pool name or Wild	cat
600 W. Illinois, Midland, Texas 79	701		Artesia; Red Lake	u.
4. Well Location				
Unit Letter 9	90 feet from the South	line and	330 féet from the	e East line
Section 28	Township 17 S Range		the second se	ity Eddy
	11. Elevation (Show whether DR, Kange			., Europ
	3680 GL	nd, ni, Un, ell	•/	
			• • • • • • • • • • • • • • • • • • •	
12. Check App	propriate Box to Indicate Natu	ire of Notice,	Report or Other Data	
		Ó P.I.		
			BSEQUENT REPOR	
		REMEDIAL WO		
				IDA L
		CASING/CEMEN	AL JOB	
OTHER:		OTHER:		П
	ed operations. (Clearly state all per		d give pertinent dates, incl	uding estimated date
	. SEE RULE 19.15.7.14 NMAC. 1			
proposed completion or recom		•		<u> </u>
1. Spot 15 sx cement @ 73)-630. WOC & Tag	·		
2. Circulate hole w/ mud la		Approved for plug	ging of well bore only.	ו
3. Perf & Sqz 35 sx @ 258-		which under ho	Differentia 1 in	
4. Cut on weinleau and weid on Dry Hole Marker. which may be fou				
				1
· · · · · · ·		forms, www.empad		
· · · · ·		Forms, www.cmnrd	.state.nm.us/ocd.	
· · · · ·		Forms, www.cmnrd	.state.nm.us/ocd.	
· · · · ·		Forms, www.cmnrd	.state.nm.us/ocd.	
· · · · ·		Forms, www.cmnrd	.state.nm.us/ocd.	
			.state.nm.us/ocd.	
	e Plussed By 7-1-2		.state.nm.us/ocd.	
Well MUST B	p Plussed By 7-1-2	016	.state.nm.us/ocd.	
Well MUST B		016	.state.nm.us/ocd.	
Spud Date:	Plussed By 7-1-2 Rig Release Da	. 016	state.nm.us/ocd.	
Spud Date:	Plussed By 7-1-2 Rig Release Da	. 016	state.nm.us/ocd.	
Spud Date:	Plussed By 7-1-2 Rig Release Da	. 016	state.nm.us/ocd.	
Spud Date:	Plussed By 7-1-2 Rig Release Da	of my knowledg	e and belief.	-13-15-
Spud Date:	Plussed By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent	of my knowledg	e and belief.	
GNATURE Bes Monta	Plussed By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent	of my knowledg	e and belief.	
GNATURE Bes Monta	Plussed By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent	of my knowledg	e and belief. DATE Auguit Tes.con PHONE:	432-580 71
GNATURE <u>Bes</u> Montgor State Use Only	Plussed By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent	of my knowledg	e and belief. DATE Auguit Tes.con PHONE:	432-580 71
Well MUST B Spud Date: Bereby certify that the information about the informatin about the informatin about the information about the informatin	Plussed By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent	of my knowledg	e and belief.	432-580 71
Well MUST B Spud Date: Breeby certify that the information about the informatin about the informatin about the information about the informatin	Plussed By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent	of my knowledg	e and belief. DATE Auguit Tes.con PHONE:	432-580 71
Image: Interest of the information about the information	Plugged By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent E-mail address: b TITLE Agent	t Difference of the second and the	e and belief. DATE Auguit Tes.con PHONE:	<u>438-580-71</u> 7-1-15
Well MUST B Spud Date: mereby certify that the information abord GNATURE Bandy - ype or print name Bandy -	Plugged By 7-1-2 Rig Release Da ove is true and complete to the best TITLE Agent E-mail address: b TITLE Agent	t Difference of the second and the	e and belief. DATE J DATE J DATE DATE	438-580-71 7-1-15

2



 NEW

 Tubing Detail (top to bottom).

 Joints
 Description

Footage Depth

Hat 32.801126 Kong - 104.171445

1 9

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: <u>COG</u>	
Well Name & Number: <u>State</u> #2	
API #: 30-0/5-2/147	、
	<u> </u>

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

7/1/2015

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100^o cement plug set 50^o above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).