Submit I Copy To Appropriate District State of New Mexico Office France Minorals and Natural Resources				Form C-103 Revised July 18, 2013			
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240				WELL API NO.			
District II - (575) 748-1283	District II $-(575)$ 748-1283				30-015-32821		
District III – (505) 334-6178					5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, District IV - (505) 476-3460	NM 87410	a Fe, NM 87		6. State Oil & Gas Lease	FEE		
1220 S. St. Francis Dr., Santa			0. State On & Gas Least	, INO.			
(DO NOT USE THIS FORM	DRY NOTICES AND REPORT FOR PROPOSALS TO DRILL OR TO	7. Lease Name or Unit Agreement Name					
DIFFERENT RESERVOIR. PROPOSALS.)	USE "APPLICATION FOR PERMIT" (	HB 2 State					
1. Type of Well: Oil V	Vell 🔲 Gas Well 🛛 Other		8. Well Number 4				
2. Name of Operator	DEVON ENERGY PRODU	9. OGRID Number 6137					
3. Address of Operator				10. Pool name or Wildcat			
	333 WEST SHERIDAN AV	ENUE, OKC,	OK 73102	Cedar Canyon, Bone Sp	ring		
4. Well Location	· · ·						
		South_line a		feet from the <u>West</u> line			
Section	2 Township		inge 29E		y New Mexico		
	11. Elevation (Show 3062'	w whether DR,	RKB, RI, GR, eic	.)			
					i Kaza		
12	. Check Appropriate Box to	o Indicate N	ature of Notice,	Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A   PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB CASING/CEMENT JOB							
CLOSED-LOOP SYSTE	EM 🛄		OTHER:				
of starting any proposed compl Devon Energy P	ed or completed operations. (Cloroposed work): SEE RULE 19. letion or recompletion. roduction Company, LP Respectfut to bring well into OCD compliance	15.7.14 NMAC	2. For Multiple Cc proval to TA the su	mpletions: Attach wellbor	e diagram of		
		, until wen ean					
Attachment:	Current & Proposed Wellbore S	Sahomatia		NM OIL CONSERVA			
Accardinent.	TA Procedure	Schematic		JUN 22 2015	•		
>		. yuuun 2200	•	JUN	•		
	successful Contact th	may be gran MIT test is p ne OCD to sc be witnessed	performed. hedule the test	RECEIVED			
$\sim$							
I hereby certify that the i	nformation above is true and con	•	-				
SIGNATURE	MOUR	TITLE <u>Reg</u>	ulatory Compliance	ce Professional DATE	06.16.15		
Type or print name Erin For State Use Only	/		workman@dvn.co		(405) 552-7970		
APPROVED BY: Conditions of Approval (	if any):	TITLE CON	nplances	OFFICAL DATE	e/25/15		

## DVN: **H B 2 State 4 API #30-015-32821 SL: 860' FSL & 1,780 FWL Sec 2-T24S-R29E** Eddy County, NM 6/9/2015

WBS #

Purpose: Temporarily Abandon Wellbore

GLM: 3,062' KBM: 3,080 KB: 18' AGL

Well spud -- 7/27/2003 T.D. - 8,410'

2

**Casing and Tubing Data:** 

Size	Wt. lb/ft	Grade	Interval	(80% S.F.) Collapse	(80% S.F.) Burst	Drift	Capacity (bbls/ft)
13-3/8"	48	H-40	0 - 542'		-	-	-
8-5/8"	32	J-55	0-3,100'	2,024	3,144	7.796	0.0609
5-1/2"	17/15.5	J-55	0-8,410'	3,232	3,848	4.767"	0.0236
2-7/8"	6.5	J-55	0 -8,149'	6,144	5,808	2.347"	0.0058

2-7/8" x 5-1/2", 15.5# csg capacity: 0.01577 bbl/ft

5-1/2" csg - DV Tool @ 6,019'

TOC outside 5-1/2" csg @ ~ 3,404' (CBL confirmed 8/19/2003)

## Existing Production string (top down):

249 Jt, 2-7/8", 6.5#, J-55 tbg 1, 2-7/8" tbg TAC (7,889') 8 jts, 2-7/8", 6.4#, J-55 tbg (253') 1, Blast Jt (3') 1, Seat Nipple (1.1') 1, 3-1/2" slotted jt (26')

**Bone Spring Perfs** 

Safety: All personnel will wear hard hats, safety glasses with side shields, and steel toed boots while on location. Assess wellhead working height for safety. If needed, use work platform or man-lift for fall protection. Tailgate safety meetings are to be held each morning prior to beginning work and prior to change in operations.


## H B 2 State 4 Recompletion Procedure:

- 1. Test and/or install and test anchors. MIRU WSU. Spot all necessary equipment. Record pressures on tbg and csg. Top kill tbg (if required) with 2% KCL
- 2. Install rod rams and TOOH w/ rods recording location and type of rod break. Fish remaining rods and pump.
- 3. ND wellhead. NU 5K BOPE with blind rams and 2-7/8" pipe rams. Test BOPE per Devon Guidelines
- 4. Release TAC (7,890') and TOOH w/ tbg. Record any wear and any paraffin/scale issues along with their location in the string.
- 5. Pick up 5-1/2" CIBP TIH to 7,955' (50' above top perf) and set CIBP. Sting out of CIBP and PU 1 jt, pressure test csg to 500 psi for 5 min to ensure CIBP is holding.

## Note: Notify State representative and Devon Engineer prior to setting CIBP.

- 6. Rig up cement truck, break circulation and spot 30 sacks of Class "H" cement on top of CIBP. Pick up 10 stands, reverse circulate 1-1/2 times tubing volume. WOC
- 7. RIH and tag cement plug. Load and test casing to 500 psi for 10 min with chart recorder. Report back to State rep and Devon engineer with tag depth and pressure test.
- 8. Circulate/roll hole with corrosion inhibiter as per Baker's recommendation.
- 9. ND BOPE, NU wellhead, RDMO WSU

DEVON ENERGY PRODUCTION COMPANY LP								
Well Name: H B 2 STATE 4	Field: PIERCE CROSSING EAST							
Location: SEC 2-T24S-R29E	County: EDDY State: NM							
Elevation: 3080'KB; 3062' GL; 18' KB-GL	Spud Date:	Compl Date:						
API#: 30-015-32821 Prepared by: Mitchel Doolin	Date: 2/9/15	Rev:						
CURRENT WELLBORE     17-1/2" hole     13-3/8", 48#, H40, STC, @ 542"     Cmt'd w/511sx to surf.     11" hole     8-5/8", 32#, J55, STC, @ 3,100"     Cmt'd w/1,025 sx. Cement to surface		Tbg Details   249 jts, 2-7/8", 6.5#, J-55 tbg (0'-7,889')   Tbg Anchor (7,890')   8 jts, 2-7/8", 6.5#, J-55 tbg (7,892'-8,146')   1 Blast Jt (8,146'-8,149')   Seat Nipple (8149)   1, 3-1/2" Slotted Jt (8,150'-8,176')   Failure History Notes:   1/24/2014-tbg split   5/17/2011-Parted Rods						
		<u>TOC @ 3,404' CBL confirmed 8/19/2003</u>						
Bone Spring Perfs 8,132'-8,005' 7-7/8" hole 5-1/2", 15.5/17#, J55, LTC, @ 8,410'								
Cmt'd w/1410 sx. Estimated TOC 2,500	8,410' TD							



.1