			~,			
·•			NM	OCD		
Form 3160-5 (August 2007)	UNITED STATE PARTMENT OF THE I	es Artesia		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM121940	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIF	PLICATE - Other instru	ctions on rev	erse side.		7. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well Image: Second state of the second state of th					8. Well Name and No. CHURCHILD FEDERAL 6	
2. Name of Operator Contact: JERRY W SHERRELL MACK ENERGY CORPORATION E-Mail: jerrys@mec.com					2. APHWETT No. 30-0157	6-1235
3a. Address P.O. BOX 960 ARTESIA, NM 88211-0960	Ph: 575-74	. (include area code 8-1288)	10. Field and Pool, or Exploratory ROUND TANK-SAN ANDRES		
4. Location of Well (Footage, Sec., T.,			11. County or Parish,	and State		
Sec 13 T15S R28E NWSE 1650FSL 1650FEL					CHAVES COU	NTY, NM
12. CHECK APPR	OPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, R	L EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	□ Acidize □ D		pen	Product	tion (Start/Resume)	U Water Shut-Off
□ Subsequent Report			ture Treat	C Reclam		□ Well Integrity
	Casing Repair	•				Other Change to Original A
Final Abandonment Notice	 Change Plans Convert to Injection 	🗆 Pluş		U Tempor	arily Abandon Disposal	PD
testing has been completed. Final Aba determined that the site is ready for fir Mack Energy proposes to drill a to spud of hole and set/cement 145-165', based on COA. 8 5/8 6.32gsl/sx Class C + 1% PF1, secured, cellar will be fenced. I	al inspection.) and set surface casing u ing of casing. A 20" hole " 32#, J-55, ST&C, New yield 1.33, weight 14.8pp	sing an Auge will be drilled casing will b og, 40% exce	rig. BLM will be to competent be set and cemer ss. Casing will b	e notified price edrock at ted w/300sx e capped an		CONSERVATION
This will eliminate the conductor pipe.					JUN 15 2015	
Conductor pipe will be set if we	ellbore issues are encour	ntered.			•••	
Accepted for record NMOCD (0//6/15					R	ECEIVED
	Electronic Submission #	RGY CORPO	ATION, sent to WEATHERFOR	the Roswell)15 (15BMW0435SE)	
Signature (Electronic St	Date 06/02/2	015				
	THIS SPACE FO	DR FEDERA	L OR STATE	OFFICE U	SE	
_Approved By_DAVID_R GLASS			TitlePETROLEUM ENGINEER Date 06/09/2015			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Roswell			
Title 18 U.S.C. Section 1001 and Title 43 U.S.tates any false, fictitious or fraudulent st				willfully to ma	ake to any department or	agency of the United
** BLM REVI	SED ** BLM REVISEI) ** BLM RE	SE	e att <i>i</i>	ACHED FO	R

PECOS DISTRICT CONDITIONS OF APPROVAL

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 15 2015

RECEIVED

OPERATOR'S NAME: Mack Energy Corporation - Sherrell, Jerry LEASE NO.: NMNM-121940 WELL NAME & NO.: CHURCHILL FEDERAL - 6 SURFACE HOLE FOOTAGE: [1650] ' F [S] L [1500] ' F [E] L BOTTOM HOLE FOOTAGE: [1650] ' F [S] L [1500] ' F [E] L LOCATION: Section 013, T015. S., R 028 E., NMPM COUNTY: Chaves County, New Mexico

1. DRILLING: DRILLING OPERATIONS REQUIREMENTS:

- A. The BLM is to be notified a minimum of 24 hours in advance for a representative to witness:
 - Spudding well,
 - Setting and/or Cementing of all casing strings,
 - BOPE tests.

The Roswell Field Office Engineer on-call phone number is: (575) 627-0205.

- B. A Hydrogen Sulfide (H2S) Drilling Operation Contingency Plan shall be activated prior to drilling into the Queen formation. A copy of the plan shall be posted at the drilling site.
- C. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- D. Include the API Number assigned to well by NMOCD on the subsequent report of setting the first casing string.
- E. The operator will accurately measure the drilling rate in feet/min to set the base of the usable water protection casing string(s) opposite competent rock. The record of the drilling rate along with the caliper-gamma ray-neutron well log run to surface will be submitted to this office as well as all other logs run on the borehole 30 days from completion.

F. Air, air-mist or fresh water and nontoxic drilling mud shall be used to drill to the base of the usable water protection casing string(s). Any polymers used will be water based and non-toxic.

CASING:

- A. Deepest depth of usable water occurs at an approximate depth of 83 feet. The 8-5/8 inch usable water protection casing string(s) shall be set in competent bedrock at the top of the salt between 145 feet and 165 feet.
 - If cement does not circulate to the surface, the Roswell Field Office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
 - Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours or 500 pounds compression strength, whichever is greater. (This is to include the lead cement).
 - Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compression strength, whichever is greater.
 - If cement falls back, remedial action will be done prior to drilling out that string.
- B. The minimum required fill of cement behind the 5-1/2 inch production casing is sufficient to circulate to the surface. If cement does not circulate, a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
- C. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- D. All casing shall be new or reconditioned and tested casing and meet API standards for new casing. The use of reconditioned and tested casing shall be subject to approval by the Authorized Officer. Approval will be contingent upon the wall thickness of any casing being verified to be at least 87-1/2 per cent of the nominal wall thickness of new casing.

PRESSURE CONTROL:

A. Prior to drilling below the 8-5/8 inch surface casing shoe, the blowout preventer assembly (BOP/BOPE) shall be installed. The BOP/BOPE shall consist of a minimum of One Annular Preventer or Two Ram-Type Preventers and a Kelly Cock/Stabbing Valve.

- B. Before drilling below the 8-5/8 inch surface casing shoe, minimum working pressure of the blowout preventer and related equipment (BOPE) shall be 2000 psi. If operator chooses to use a control device greater than the minimum stand they will have to follow all guidelines as stated within Bureau of Land Management 43 CFR part 3160 and Onshore Oil and Gas Order No. 2 Drilling Operations.
- C. The BOPE shall be installed before drilling below the 8-5/8 inch surface casing shoe and shall be tested as described in Onshore Oil and Gas Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced.
 - The BLM Roswell Field Office shall be notified a minimum of 24 hours in advance for a representative to witness the tests.
 - The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.
 - All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test will be submitted to the BLM Roswell Field Office at 2909 West Second Street, Roswell, New Mexico 88201.
 - Testing fluid must be water or an appropriate clear liquid suitable for sub-freezing temperatures. Use of drilling mud for testing is not permitted since it can mask small leaks.
 - Testing must be done in a safe workman like manner. Hard line connections shall be required.
 - The requested variance to test the BOPE prior to drilling below the 8-5/8 inch surface casing to the reduced pressure of 2000 psi by a third party is approved.

2. CLOSED LOOP SYSTEMS:

No reserve pit will be used. Steel tanks are required for drilling operations. The operator shall properly dispose of drilling contents at an authorized disposal facility. No open top tanks are permitted.