

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD JUN 29 2015

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on reverse side.**

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NNMN0375257
2. Name of Operator OXY USA INC.		6. If Indian, Allottee or Tribe Name
3a. Address P.O. BOX 50250 MIDLAND, TX 79710		7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) Ph: 432-685-5717 Fx: 432-685-5742		8. Well Name and No. AVALON FEDERAL 2
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 18 T21S R27E NWSE 1980FSL 1980FEL 32.478140 N Lat, 104.227030 W Lon		9. API Well No. 30-015-21491
		10. Field and Pool, or Exploratory BURTON FLAT MORROW
		11. County or Parish, and State EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

4/14/15 MIRU PU, ND WH, NU BOP, Notify Jim Amos-BLM. Unload tbg.

4/15/15 Circ hole w/ 10# BW, RIH w/ muleshoe, tag parted csg @ 2882', work thru, continue in hole & tag up @ 7959'.

4/16/15 RIH & tag TOF @ 10896', SI WO orders

4/20/15 Contact Jim Amos-BLM, rec approval to spot 1st plug on TOF @ 10896'. Circ wellbore w/ 10# MLF, M&P 30sx CI H cmt @ 10896-10615', PUH, WOC.

4/21/15 RIH & tag cmt @ 10602', Robert Girndt-BLM, on location. PUH to 10527', circ hole w/ 10# MLF, M&P 30sx CI H cmt @ 10527-10256', PUH, WOC. RIH & tag cmt @ 10271', Terry Wilson-BLM on

Accepted for record
OCD NMOC 7/31/15Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.RECLAMATION
DUE 11-17-15

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #302862 verified by the BLM Well Information System
For OXY USA INC., sent to the Carlsbad

Name (Printed/Typed) DAVID STEWART	Title SR. REGULATORY ADVISOR
Signature (Electronic Submission)	Date 05/26/2015

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	JUN 22 2015

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any statement or representation as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #302862 that would not fit on the form

32. Additional remarks, continued

location, M&P 30sx CI H cmt @ 10090-9819', PUH, WOC.

4/22/15 RIH & tag cmt @ 9810', PUH to 9613', M&P 30sx CL H cmt @ 9613-9342', PUH, WOC. RIH & tag cmt @ 9341', Robert Girndt-BLM on location. POOH w/ tbg to 3166'.

4/23/15 ND BOP, NUWH, RD plugging equipment, w/o pulling unit to finish plugging job.

5/5/15 MIRU PU, ND B-1 Adap, NU BOP, Notify Jim Amos-BLM.

5/6/15 RIH w/ mill, drill collars, tbg, work though bad spot @ 2882', RIH to 8749'.

5/7/15 POOH & LD drill collars & mill, RIH w/ pkr & set @ 5255', BOT @ 8238', pressure test csg @ 5255-9341' (last plug) to 500#, tested good.

5/12/15 RIH w/ tbg & pkr to 8617', Rec appr-Jim Amos to spot plug instead of perf. M&P 10# MLF, PUH to 8743', M&P 40sx CL H cmt, PUH, WOC.

5/13/15 RIH & tag cmt @ 8269', PUH to 6339', pkr @ 3386'. RIH w/ WL & perf @ 6795', EIR, M&P 50sx CL H cmt w/ full returns up 9-5/8" X 5-1/2", WOC.

5/14/15 Attempt to release pkr, stuck. RIH w/ WL & tag EOT @ 6330', PUH & perf 2 holes above pkr @ 3364', EIR @ .75 BPM @ 1350# w/ no circulation. Work pkr & tbg to 110000#, would not release. RIH w/ free point, tbg 100% free @ 5000', 100% stuck @ 5150'. RIH & cut tbg @ 5000', rel pkr & POOH. RIH & perf csg @ 4890', RIH & set pkr @ 4435', EIR @ 2BPM @ 0# w/ full returns, M&P 50sx CL C cmt, PUH, WOC.

5/15/15 RIH & tag cmt @ 4600', POOH w/ tbg.

5/18/15 ND BOP, ND A sec WH, PU csg spear, on csg @ 140000#, csg pulled free. NU WH, NU BOP, RU csg tools.

5/19/15 POOH w/ 77 jts 5-1/2" 17-20# N-80 csg. RD csg tools, RIH w/ tbg to inside csg stub @ 2875' to 1942'.

5/20/15 RIH w/ tbg to 2943', circ 10# MLF, M&P 130sx CI C cmt w/ 2% CaCl₂, POOH, WOC. RIH & tag cmt @ 2600'. PUH to 1148', M&P 50sx CL C cmt w/ 2% CaCl₂, POOH, WOC.

5/21/15 RIH & tag cmt @ 988', PUH to 670', M&P 230sx CL C cmt, circ to surface. RD BOP & top spool of WH, top off csg w/ cmt, RDPU.