	UNITED STATE DEPARTMENT OF THE I BUREAU OF LAND MANA	INTERIOR	OCD Artesia	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 se Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			· • • • • • • • • • • • • • • • • • • •	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
I. Type of Well □ Oil Well ⊠ Gas Well	☐ Other	· · · · · · · · · · · · · · · · · · ·		Name and No. DD 23A FEDERAL 38	
2. Name of Operator Contact: REBECCA DEAL DEVON ENERGY PRODUCTION CO EPMail: REBECCA.DEAL@DVN.COM				9. API Well No. 30-015-35076-00-S1	
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102		Ph: 405-228-8429 SAN		Field and Pool, or Exploratory SAND DUNES	
4. Location of Well (Footage, Sec 23 T23S R31E NEN	Sec., T., R., M., or Survey Descriptio. E 660FNL 860FEL	n)		ounty or Parish, and State DY COUNTY, NM	
h 12. CHECK	APPROPRIATE BOX(ES) T	O INDICATE NATURE OF	NOTICE, REPORT	, OR OTHER DATA	<u> </u>
TYPE OF SUBMISSION	· · · · · · · · · · · · · · · · · · ·	ТҮРЕ (OF ACTION		
 ☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Not 	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	 Deepen Fracture Treat New Construction Plug and Abandon Plug Back 	 Production (State Reclamation Recomplete Temporarily Al Water Disposal 	□ Well In □ Other pandon	
If the proposal is to deepen dir Attach the Bond under which the following completion of the in	ted Operation (clearly state all pertine rectionally or recomplete horizontally the work will be performed or provid wolved operations. If the operation r	 give subsurface locations and mea e the Bond No. on file with BLM/B 	sured and true vertical de A. Required subsequent	pths of all pertinent markers a reports shall be filed within 3	nd zones. 0 days
determined that the site is read	ly for final inspection.)	iled only after all requirements, inclu	iding reclamation, have b	een completed, and the opera	tor has
determined that the site is read Devon Energy Productio the following procedures -Test Anchors -MIRU WSU -ND WH, NU BOPE and -Unset Packer and TOH -MIRU WL unit & make g -Run Gyro Survey to 13,	ly for final inspection.) in Company, LP respectfully re test w/ 2-3/8? tubing gauge run to 13,700? KBM 680? KBM	iled only after all requirements, inclue equests to run an MIT on the	referenced well with	CHEDFOR NS OF APPR	ord (3/1) VAL
determined that the site is read Devon Energy Productio the following procedures -Test Anchors -MIRU WSU -ND WH, NU BOPE and -Unset Packer and TOH -MIRU WL unit & make g -Run Gyro Survey to 13,	ly for final inspection.) in Company, LP respectfully re test w/ 2-3/8? tubing gauge run to 13,700? KBM 680? KBM condition of casing and ceme at 12,387? KBM)	iled only after all requirements, inclue equests to run an MIT on the	referenced well with SEE ATTA CONDITIO	CHEDFOR	
determined that the site is read Devon Energy Productio the following procedures -Test Anchors -MIRU WSU -ND WH, NU BOPE and -Unset Packer and TOH -MIRU WL unit & make of -Run Gyro Survey to 13, -Run USIT/CBT to verify (Note - Top of 5.5? liner -RIH and WL set CIBP (test w/ 2-3/8? tubing gauge run to 13,700? KBM 680? KBM condition of casing and ceme at 12;387? KBM) 13680? KBM 13680? KBM Condition of casing and ceme at 12;387? KBM) 13680? KBM Condition of casing and ceme at 12;387? KBM Electronic Submission For DEVON ENER Committed to AFMSS for proce	equests to run an MIT on the equests to run an MIT on the ent bond to 13,680 ? KBM with bond to 13,680 ? KBM with bond to 13,680 ? KBM with bond to 13,680 ? KBM	Iding reclamation, have the referenced well with SEE ATTA CONDITIO	CHEDFOR CHEDFOR NS OF APPR ARTESTA DISTR AUG 3 201 RECEIVED	
determined that the site is read Devon Energy Productio the following procedures -Test Anchors -MIRU WSU -ND WH, NU BOPE and -Unset Packer and TOH -MIRU WL unit & make g -Run Gyro Survey to 13, -Run USIT/CBT to verify (Note - Top of 5.5? liner -RIH and WL set CIBP (test w/ 2-3/8? tubing gauge run to 13,700? KBM 680? KBM condition of casing and ceme at 12;387? KBM) 13680? KBM 13680? KBM Condition of casing and ceme at 12;387? KBM) 13680? KBM Condition of casing and ceme at 12;387? KBM Electronic Submission For DEVON ENER Committed to AFMSS for proce	equests to run an MIT on the equests to run an MIT on the ent bond to 13,680 ? KBM with bond to 13,680 ? KBM with bond to 13,680 ? KBM with bond to 13,680 ? KBM	referenced well with SEE ATTA CONDITIO	CHEDFOR CHEDFOR NS OF APPR ARTESTA DISTR AUG 3 201 RECEIVED	
determined that the site is read Devon Energy Productio the following procedures -Test Anchors -MIRU WSU -ND WH, NU BOPE and -Unset Packer and TOH -MIRU WL unit & make g -Run Gyro Survey to 13, -Run USIT/CBT to verify (Note - Top of 5.5? liner -RIH and WL set CIBP (Additional) 14. Thereby certify that the foreg	test w/ 2-3/8? tubing gauge run to 13,700? KBM 680? KBM condition of casing and ceme at 12;387? KBM) 13680? KBM 13680? KBM 13680? KBM Condition of casing and ceme at 12;387? KBM) 13680? KBM Condition of casing and ceme at 12;387? KBM Electronic Submission i For DEVON ENER Committed to AFMSS for proce ECCA DEAL	ant bond to 13,680 ? KBM which is the second	referenced well with SEE ATTA CONDITIO	CHEDFOR CHEDFOR NS OF APPR ARTESTA DISTR AUG 3 201 RECEIVED	
determined that the site is read Devon Energy Productio the following procedures -Test Anchors -MIRU WSU -ND WH, NU BOPE and -Unset Packer and TOH -MIRU WL unit & make g -Run Gyro Survey to 13, -Run USIT/CBT to verify (Note - Top of 5.5? liner -RIH and WL set CIBP (-RIH and WL set	test w/ 2-3/8? tubing gauge run to 13,700? KBM 680? KBM condition of casing and ceme at 12;387? KBM) 13680? KBM 13680? KBM 13680? KBM 13680? KBM 13680? KBM Condition of casing and ceme at 12;387? KBM) 13680? KBM Condition of casing and ceme at 12;387? KBM Condition of casing and ceme Electronic Submission in For DEVON ENER Committed to AFMSS for proce ECCA DEAL tronic Submission) THIS SPACE F attached. Approval of this notice doc I or equitable title to those rights in the	ent bond to 13,680 ? KBM ant bond to 13,680 ? KBM #308663 verified by the BLM W GY PRODUCTION CO LP, sen rssing by JENNIFER SANCHEZ Title REGL Date 07/09 OR FEDERAL OR STATE S not warrant or he subject lease Office	referenced well with SEE ATTA CONDITIO	CHED FOR CHED FOR NS OF APPR ARTESIA DISTR AUG 3 201 RECEIVED MCE PROF	ior has

.


,


Additional data for EC transaction #308663 that would not fit on the form

32. Additional remarks, continued,
-Dump bail 35? Cement on top of CIBP, estimating new PBTD at 13,645? KBM
-RD WL
-TIH with SN and 2-7/8? tubing to 13,600? KBM.
-Load and circulate hole with 2% KCL and corrosion inhibitor
-Test 5-1/2? casing and CIBP w/ cement plug to 500 psi at surface for 30 minutes, chart test and have BLM witness test
-Bleed off pressure, ND BOPE, NU WH
-RDMO WSU
-Shut-in well

TA?ing well to bring well into OCD compliance, until well can be evaluated. Devon respectfully requests a 2 year LA status for the captioned well.

Attached: Current and Proposed Wellbore Schematics.





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street * Carlsbad, New Mexico 88220 575-234-5972

Work to be completed by 10/28/2015.

- 1. Operator shall set a CIBP at 13,680 (50' above top most perf) and <u>place 240' Class H</u> <u>cement on top.</u>
- 2. Operator shall place a solid Class H cement plug from 12,750'-12,337' to seal the 7-5/8'' casing shoe and the 5-1/2'' liner top. If operator desires this well to be a Wolfcamp producer this step can be done at a later date via sundry submittal.

<u>Note:</u> If operator does not produce from the Wolfcamp or Bone Spring formations a sundry will need to be submitted to properly plug back these formations.

TA status approved for a period of 12 months ending 10/28/2016 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.

2. A procedure to plug and abandon the well.

Todd 23A Federal 38

- 1. Well is approved to be TA/SI for a period of 12 months or until 10/28/2016
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 010/28/2016
- 4. COA's met at this time.