Form 3160-5

N.M. Oil Cons. DIV-Dist. 2 1301 W. Grand Avenue

FORM APPROVED DEPARTMENT AND SIGNAM 88210 OMB No 1004-0137 Expires: March 31, 2007 (April 2004) BUREAU OF LAND MANAGEMENT 5. Lease Serial No. NM 98120 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side Skelly Unit Type of We Gas Well 8 Well Name and No. 2. Name of Operator The Wiser Oil Company API Well No. 30-015-05148 3a 3b. Phone No. (include area code) Address 3504 West County Road Hobbs, New Mexico 88240 505 392-9797 10 Field and Pool, or Exploratory Area RECEIVED Grayburg Jackson 7-Rivers QN-GB-SA 4. Location of Well. (Footage, Sec., T. R., M., or Survey Description) 11 County or Parish. State 14-175-31E 560' FNL & 1980' FWL OCT 2 6 2005 Unit C Eddy County, New Mexico ALBE I TAPQOO 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Water Shut-Off Deepen ☐ Notice of Intent Well Integrity Alter Casing Reclamation Fracture Freat Other Repair packer Casing Repair New Construction Recomplete ✓ Subsequent Report Temporarily Abandon Change Plans Plug and Abandon Final Abandonment Notice Water Disposal Convert to Injection Plug Back 13. Describe Proposed or Completed Operation relearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 7/01/05 MIRU unit. ND WH. NU BOP. POH w/pkr. & 2-3/8" tbg. 7/05/05 RIH w/RBP & pkr. Set RBP @ 3349'. Set pkr. @ 3291'. Test RBP to 1200 PSI. Held ok. Test csg. to 550 PSI for 30 min. Held ok. Unset pkr. RIH & latch on to RBP. Unset RBP & POH. 7/06/05 RU testers. Hydrotest tbg, to 3000 PSI. Set pkr. @ 3353'. Pressure annulus to 500 PSI for 20 min. Held ok. Release pkr. Circulate pkr. fluid. Reset pkr. ND BOP. NU WH. Pressure annulus to 500 PSI. Held ok. RD unit. 7/15/05 MIRU unit, ND WH, NU BOP, Released pkr, POH w/tbg, & pkr. 7/18/05 R1H w/pkr. & 2-3/8" tbg. Pressure annulus to 500 PSI for 25 min. Held ok. Released pkr. Circulate pkr. fluid. Reset pkr. @ 3352'. ND BOP. NU WH. Pressure annulus to 500 PSI. Held ok. 9/16/05 Chart performed by Nick Jimenz with Gandy Corporation. Witnessed by NMOCD Artesia Office. Copy of chart attached. Original chart to NMOCD. ACCEPTED FOR RECORD 14. Thereby certify that the foregoing is true and correct Name (Printed Typed) Mary Jo Turner Title Production Analyst ALEXIS C. SWOBODA PETROLEUM ENGINEER

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any dept ment or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its inclediation Accepted Ros

