Submit 3 Copies State of New Mexico to Appropriate Company State of New Mexico Energy, Minerals and Natural Resources Department of the Company State of New Mexico	rtment Form C-103 Revised 1-1-89
CONCEDIATION DIVICIONI	
P.O. Box 1980-Hobbs NM 88241 1980 2040 Pacheco St.	WELL API NO.
DISTRICT II O RECEIVE SIA SIA SANTA Fe, NM 87505 P.O. Drawer D. Arte COMM 88210	30.015.00724  5. Indicate Type of Lease
DISTRICT III  1000 Rio Brazos Riv. Aztec, NM 87410 (1)  SI DI SI ZI	STATE X FEE   6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Empire Abo Unit "I"
1. Type of Well: OIL GAS WELL OTHER	
2. Name of Operator	8. Well No.
BP America Production Company	16
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	9. Pool name or Wildcat Empire Abo
4. Well Location	N. N.
Unit Letter A: 330 Feet From The E Line and 990 Feet From The N Line	
Section 02 Township 18S Range 27E NMPM / Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEI	MENT JOB
OTHER: OTHER:	
12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
TD: 5920' PBD: 5877' PERFS: 5872-5773'	
MIRUPU. NDWH. NUBOP. RUWL. RIH w/SV & set in SN @ 5624'. POH. GIH & chem cut 2-3/8" tbg in 2nd jt. above pkr. POH w/wireline & chem cutter. RHWL. POH w/tbg. GIH w/overshot, SN & 2-3/8" WS to top of fish. Swab well down to SN. If necessary kill well w/1 bbl 2% KCL wtr. GIH to catch fish. Rls pkr. POH. RIH w/bit & scraper to PBTD @ 5877'. POH. GIH & perf w/2 JSPF 5592-5734'. GIH w/PPI tools & breakdown perfs f/5734-5592' w/50 gals/ft. 15% HCL NEFE. POH. RIH w/prod. assy. Land 2-3/8" tbg @ +/- 5837'. NDBOP. NUWH. Swab for test. RTP.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
$\mathcal{K}$ if $\mathcal{M}$	ive Assistant DATE05.22.03
TYPEOR PRINT NAME Kellie D. Murrish	TELEPHONE NO. 505,394,1649
(This space for Subjects)  APPROVED BY  CONDITIONS OF APPROVAL, IF ANY:	igaviser JAN 0 2 2003