

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave., Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO.
30-005-63612

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

BRIAN FEE

8. Well No.

2

9. Pool Name or Wildcat

Race Track San Andres, East

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

MAR 20 2004

OCD-ARTESIA

1. Type of Well:

OIL

GAS

WELL ☒

WELL ☐

OTHER

2. Name of Operator

ELK OIL COMPANY

3. Address of Operator

POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310

4. Well Location

Unit Letter

C

:

330

Feet From The

NORTH

Line and

2310

Feet From The

WEST

Line

Section

19

Township

10 SOUTH

Range

29 EAST

NMPM

CHAVES

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3896' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103

PLUG AND ABANDON WELL AS FOLLOWS:

- (1) SET 35 SXS PLUG AT 2805'.
- (2) SET 35 SXS PLUG AT 1105'.
- (3) SET 50 SXS PLUG AT 450'. WOC. TAG AT 325'.
- (4) SET 15 SXS (60") SURFACE PLUG.
- (5) WAIT 24 HOURS. TOP SURFACE PLUG OFF.
- (6) INSTALL DRY HOLE MARKER.

NOTE: VERBAL APPROVAL FROM MIKE BRATCHER, NMOC D TO ROCKY RAY, ELK OIL COMPANY
TO PLUG WELL ON 03/24/04 AT 10:00 A.M.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

PRESIDENT

DATE

3/29/04

TYPE OR PRINT

NAME

JOSEPH J. KELLY

TELEPHONE NO.

505-623-3190

(This space for State Use)

Field Supervisor

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

NOV 16 2005



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

12 April 2004

Elk Oil Co.

P.O. Box 310

Roswell, New Mexico 88202-0310

Form C-103 Report of Plugging for your Brian Fee # 2 C-19-10-29 API 30-005-63612
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name

Title


Van Barton
Field Rep. II