Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-015-29376 District II OIL CONSERVATION DIVISION 5. Indicate Type of Lease 1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr. District III STATE X FEE □ 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH **OXY Mustang State** PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well X Other 9. OGRID Number 2. Name of Operator OXY USA WYP Limited Partnership 192463 10. Pool name or Wildcat 3. Address of Operator OOU MATERIA P.O. Box 50250 Midland, TX 79710-0250 Turkey Track Atoka 4. Well Location 1980 feet from the south feet from the\_\_\_ line Unit Letter line and **NMPM** 16 Township 185 Range 29E County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3519' Pit or Below-grade Tank Application or Closure Pit type Steel Depth to Groundwater N/A Distance from nearest fresh water well N/A Distance from nearest surface water N/A N/A Pit Liner Thickness: \_\_ Below-Grade Tank: Volume\_\_\_\_ \_bbls; Construction Material \_ 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING X**CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG AND TEMPORARILY ABANDON ABANDONMENT PULL OR ALTER CASING MULTIPLE** CASING TEST AND CEMENT JOB COMPLETION OTHER: Set CIBP & Run CIT X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. OXY USA WTP LP requests to temporarily abandon this well for possible future use. Notify OCD 24 hours TD-11300' PBTD-11241' Perfs-10656-10686' Pkr-10583' prior to test, 748-1283 1. Notify BLM/NMOCD of casing integrity test 24hrs in advance. 2. RIH. POOH w/ pkr and tbg. RIH and set CIBP @ 10556' 3. RU pump truck, circulate well with treated water, pressure test casing for 30 min and TA well. PER PULS 203 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines \_\_\_\_\_, a general permit \_\_\_\_or an (attached) alternative OCD-approved plan \_\_\_\_\_ TITLE Sr. Regulatory Analyst DATE ULY(65 SIGNATURE\_\_ Telephone No. 432-685-5717 NOV 16 2005 E-mail address: david stewart@oxy.com Type or print name David Stewart Field Supervisor For State Use Only

TITLE

DATE

APPROVED BY

Conditions of Approval, if any: