

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NMOCD

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator  
J.C. WILLIAMSON3a. Address  
P.O. Box 16, Midland, TX 797023b. Phone No. (include area code)  
(432) 682-17974. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
1980' FNL & 660 FWL  
Sec. 27 T 26S - R 30E

5. Lease Serial No.

NM 0555443

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

ROSS DRAW UNIT

8. Well Name and No.

ROSS DRAW #10

9. API Well No.

30-015-23579

10. Field and Pool, or Exploratory Area  
Morrow

11. County or Parish, State

Eddy, NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION                                   | TYPE OF ACTION                                |                                                      |                                                    |                                         |
|------------------------------------------------------|-----------------------------------------------|------------------------------------------------------|----------------------------------------------------|-----------------------------------------|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen                      | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Subsequent Report           | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat              | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice    | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction            | <input type="checkbox"/> Recomplete                | <input type="checkbox"/> Other          |
|                                                      | <input type="checkbox"/> Change Plans         | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |                                         |
|                                                      | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back                   | <input type="checkbox"/> Water Disposal            |                                         |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

NOTE: Verbally <sup>discussed</sup> ~~approved~~ P & A in January, 2005 with Alexis Swoboda.

Please see attached procedure.

RECEIVED

JAN 18 2006

UUU-AMTSDM

ENTERED IN  
AFMSS14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Roger Massey

Title AGENT

1-9-06

Signature

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (ORIG. SCD.) ALEXIS C. SWOBODA

PETROLEUM ENGINEER

JAN 12 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18, U.S.C. Section 1001 and Title 43, U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

APPROVAL SUBJECT TO  
GENERAL REQUIREMENTS AND  
SPECIAL STIPULATIONS ATTACHEDAccepted for return  
NMOCD

J. C. Williamson

Ross Draw Unit #10  
Eddy County, New Mexico

- (1) MIRU. Will need mat.
- (2) Establish IR under pkr. @ 12,126'.
- (3) Sqz. 175 sx Class H under pkr. & displace to 12,150' WOC & test. Covers perf. & 7-5/8" shoe.
- (4) Un -J off of pkr. Circ. hole w/ MLF (525 bbls.).
- (5) Spot 25 sx Class H cmt. 12,126-12,026'. WOC & tag. Top of pkr.
- (6) Pull tbg. to 11,350', spot 25 sx Class H 11,350-11,250'. 10-3/4" shoe.
- (7) Pull tbg. to 10,915', spot 65 sx Class H 10,915-10,615', WOC & tag. Liner top/Wolfcamp.
- (8) POOH w/ tbg.
- (9) NU WH & weld onto 7-5/8" csg.
- (10) Cut 7-5/8" csg. @ 7300'.
- (11) POOH & LD 7300' of 7-5/8" csg. (Note: Only 13 hrs. allowed to LD).
- (12) RIH w/ tbg. to 7350', spot 40 sx 7350-7250', WOC & tag. Stub & Bone Spring plug.
- (13) POOH w/ tbg.
- (14) ND WH & weld onto 10-3/4" csg.
- (15) Cut 10-3/4" csg. @ 3375'.
- (16) POOH & LD 3375' of 10-3/4". (Note: May have to cut csg. w/ torch. Also, only 15 hrs. allowed to LD csg.).
- (17) RIH w/ tbg. to 3425', spot 65 sx 3425-3325', WOC & tag shoe & stub.
- (18) Pull tbg. to 450', spot 80 sx 450-350', WOC & tag.
- (19) Pull tbg. to 60', spot 40 sx 60-3'.
- (20) RDMO. Cut off WH, install dry hole marker, & clean location.