Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Serial No.
Do not use this form for proposals to drill or to re-enter an	NMLC64050A
abandoned well. Use Form 3160-3 (APD) for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	
	7. Unit or CA Agreement Name and No.
1a. Type of Well 🗸 Oil Well 🗌 Gas Well 🔲 Other	8 Well Name and No.
2. Name of Operator	Eagle 34 ! Federal 32
DEVON ENERGY PRODUCTION COMPANY, LP	9. API Well No.
3. Address and Telephone No.	30-015-31747
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198	10. Field and Pool, or Exploratory
4. Location of Well (Report location clearly and in accordance with Federal requirements)*	Red Lake Glorieta-Yeso, NE
1650 FSL 990 FEL	12. County or Parish 13. State
SEC 34 T17S R27E, UNIT I	Eddy NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	<del>-1</del>
TYPE OS SUBMISSION TYPE OF ACTIO	
Acidize Deepen Product	tion (Start/Resume) Water Shut-Off
Alter Casing Fracture Treat Reclam	· · ·
☐ Subsequent Report ☐ Casing Repair ☐ New Construction ☑ Recomp	· <del></del>
Final Adandonment Notice	rarily Abandon
Convert to Injection Plug Back Water I  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting	Disposal any proposed work and approximate duration thereof. If the proposal
deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones.	Attach the Bond under which the work will be performed or provide
the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has	
determined that the site is ready for final inspection)	
	1
Devon Energy Production Company, LP hereby requests approval to recomplete to the Queen-Grayburg-San Andres per the following procedure:	
1. MIRU PU. TOH with rods and pump. ND tree, NU BOP. TOH with tubing.	
2. Pick up RBP and RIH on tubing. Set RBP at +1- 2850'. TOH with tubing.	
3. PU bailer and RIH on tubing. Dump 10 sand on top of RBP. TOH with tubing.	
4. MIRU pump truck. Pressure test RBP and casing to 4000 psi.	
5. RIH with 3-1/8" casing gun and perforate the San Andres w/ 40 holes from 1800'-2500'. TOH with	
wireline RDMO same	
6. MIRU BJ. Acidize & frac San Andres perfs.	APPROVED   I
7. Open well up and flow back frac load until well dies.	
9. RIH with SN, with nothing below it. Set SN +/-15' below bottom perf.	
10. RIH with pump and rods. Hang well on and put well to test to battery.	JAN 1 1 2006
	G. SGD.) ALEXIS C. SWOSODA
(Out	
	ALEXIS C. SWOBODA PETROLEUM ENGINEER
	THOUSE OF THE STATE OF THE STAT
14.∕⊤hereby certify that the foregoing is true and correct	
Signed Name Norvella Adams Title Sr. Staff Engineering Technician	Date 12/30/2005
(This space for Federal or State Office use)	
Approved by Title	Dete
Conditions of approval, if any:	Date
Conditions of approvar, if any.	Date
Conditions of approval, if any.  The 16 C.S.C. Section 1001, makes it a crime for any person knowingly and wanting to make any department of agency of the orinted states any rai	