Form 3160-5 (September 2001) Complimentory Copy

15161772

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

	Exp	ires J	anuary	31,	2004
Lease	Serial	No.			

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. NMNM-18970
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.				
Type of Well Sol Oil Well Gas Well Other			S SUN 2003 ES			8. Well Name and No.			
Read & Stevens, Inc. 3a. Address		3b.	3b. Phone No. (include area code)		West Haystack Federal #5 9. API Well No. 30-005-62991				
4 Location of Well (Footage, Sec. 1650 FNL & 2100	Roswell, NM 88202 T. R. M. or Survey Description PWL R27E		505/622-37	150	5 20 0 0 1	Hayst	or Pa	ol, or Exploratory Area k Cisco Arish, State County, New Mexico	
12. CHECK AP	PROPRIATE BOX(ES) To	O INE	DICATE NATUR	RE O	F NOTICE, RE	PORT, O	R O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	000	Deepen Fracture Treat New Construction Plug and Abandon	0000	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon		000	Well Integrity	
Final Abandonment Notice	Convert to Injection	Q 5	Plug Back	<u></u>	Water Disposal Pending P&A starting date of any proposed work and approximate duration there				

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

05/29/03 MIRUSU. RIH w/ 5 ½" CIBP and set @ 5,500'. Perforate 2 SPF @ 1,878'-94', 1,902'-08', total of 46 holes. Acidize w/ 1,000 gal 15% NEFe HCl spacing 58 BS's throughout job. Swab water, no show oil. Perforate 2 SPF @ 1,584'-92', total of 17 holes. Set RBP @ 1,805'. Close BOP. Acidize w/ 1,000 gal 15% NEFe HCl via tbg spacing 22 BS's throughout job. Swab water w/ slight show of oil. RIH w/ retrieving head, tbg. Catch and rls RBP. POOH laying down tbg and RBP. NDBOP. NUWH. RDMOSU. SWI pending plug and abandonment.

	8				
14 I hereby certify that the foregoing is true and Name (Printed/Typed)	correct				
John C. Maxey, Jr.	<u>,</u>	Title	Operati	ons Manager	
Signatur		Date	6 -1 2-03		
	THIS SPACE FOR	FEDERAL OR	STATE OFFICE	JSE	
Approved by			Title	Date	
Conditions of approval, if any, are attached. A certify that the applicant holds legal or equitable which would entitle the applicant to conduct oper	le title to those rights in	Abr	Office		
					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.