

OCD-ARTESIA  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

## SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well  
☐ Oil Well ☐ Gas Well ☒ Other2. Name of Operator  
Merit Energy Company3a. Address  
13727 Noel Road, Suite 500, Dallas, Texas 752403b. Phone No. (include area code)  
972-628-16104. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
660' FSL & 1980' SWL, Sec. 5, T-17-S, R-31-E

5. Lease Serial No.

LC-029435-B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Keel, J. L. "B" Well No. 11

9. API Well No.

30-015-05077

10. Field and Pool, or Exploratory Area  
Grayburg-Jackson

11. County or Parish, State

Eddy County, New Mexico

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	


13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. CIBP's Set at 2905' and CIBP set @ 1525'. CIBP @ 1525' has 10' cement plug on top. Work completed on 2/01/2006.

02/10/2006 - MIRU, Test well for TA. Well tested for 30 minutes. Tested OK. Test witnessed by NMOCD Field Inspector. Original chart to NMOCD Artesia. Copy attached for your records. RDMO, Clean location.

BLM - Request Temporarily Abandonment Status.

NMOCD - Request Temporarily Abandonment Status for a period not to exceed 5 years.



APPROVED FOR 12 MONTH PERIOD  
ENDING 2/15/07

like Sundry dated  
2/7/06

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Larry M. Sanders

Title Sr. Regulatory Analyst

Signature

Date

02/23/2006

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.


Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



Send ORIGINAL chart w/C-103 to  
OCD requesting temporary abandon  
status. Show procedure used to  
prepare well for T/A

GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

CHART NO. MC MP-1000

METER  
TA 7237

CHART PUT ON

J-10-06

LOCATION J.L. K&L B #11

REMARKS 30-015-06077

*pony*

TYPE H GRAPH