UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM27277

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Gas-Well □ Other					8. Well Name and No. LEO 15 B2DN FED COM 1H	
2. Name of Operator Contact: JACKIE LATHAN MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com					9. API Well No. 30-015-43312-00-X1	
3a. Address 3b. Phone No P O BOX 5270 Ph: 575-39 HOBBS, NM 88241			include area code) 10. Field and Pool, or Exploratory LOCO HILLS		Exploratory	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State	
Sec 15 T18S R30E NWNW 630FNL 370FWL					EDDY COUNTY, NM	
12. СНЕСК АРРГ	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF N	NOTICE, RI	EPORT, OR OTHER	DATA
TYPE OF SUBMISSION	OF SUBMISSION . TYPE OF ACTION					
➡ NI-4'. CT.	☐ Acidize ☐ Deep		pen Product		ion (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing	☐ Alter Casing ☐ Frac		ture Treat		■ Well Integrity
Subsequent Report	☐ Casing Repair ☐ Nev		Construction Recomp		olete	Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Plu		-		rarily Abandon Well Spud	
	☐ Convert to Injection ☐ Plug		_ •			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 9/11/2015 Spud 17 1/2" hole. TD hole at 455'. Ran 455' of 13 3/8" 54.5# J55 ST&C Csg. Cemented with 500 sks Class C w/ additives. Mixed @ 14.8#/g w/1.34 yd. Circ 95 sks of cmt to the pit. WOC. Tested BOPE & Annular to 2000#. At 12:45 a.m. 9/13/15, tested csg to 1500# for 30 min, held OK. Drilled out w/ 12 1/4" bit. NM OIL CONSERVATION ARTESIA DISTRICT OCT 1 3 2015 RECEIVED ACCEPTED AND MANAGEMENT RECEIVED 14. I hereby certify that the foregoing is true and correct. Electronic Submission #316678 verified by the BLM Well Information Systems.						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #316678 verified by the BLM Well Information For MEWBOURNE OIL COMPANY, sent to the Carlsback Committed to AFMSS for processing by ED FERNANDEZ on 10/06/2015 (16EF0004SE)	
Name(Printed/Typed) JACKIE LATHAN			Title AUTHORIZED REPRESENTATIVE			
Signature (Electronic Submission)			Date 09/16/2015			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE	
Approved By ACCEPTED			EDWARD FERNANDEZ TitlePETROLEUM ENGINEER Date 10/06/2015			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or tertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad			
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to m	ake to any department or a	agency of the United

MAN WELDING SERVICES, WE

Compan

0 11

Drilling Contractor

ug & Drill Pipe

Accumulator Pressure:

Manifold Pressure: 1500

Annular Pressure: ///00

Acc ulator F nctio

st -

&G #2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

Make sure all rams and annular are open and if applicable HCR is closed. Ensure accumulator is pumped up to working pressure! (Shut off all pumps)

- 1. Open HCR Valve. (If applicable)
- 2. Close annular.
- 3. Close all pipe rams.
- 4. Open one set of the pipe rams to simulate closing the blind ram.
- 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).

6. Rec

psi.

s if pressure is lower than required.

b. { for a 2000 & 3000 psi system }

7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:

- a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
- 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
- 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
- 3. Record pressure drop_/000_psi. Test fails if pressure drops below minimum.

Minimum: a. (700 psi for a 1500 psi system) b. [900 psi for a 2000 & 3000 psi system]

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

Isolate the accumulator bottles or spherical from the pumps & manifold.

Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve

- 1. Open the HCR valve, (if applicable)
- 2. Close annular
- 3. With pumps only, time how long it takes to regain the required manifold pressure.
- 4. Record elapsed time 1148. Test fails if it takes over 2 minutes.
 - a. [950 psi for a 1500 psi system] b. [1200 psi for a 2000 & 3000 psi system]