Submit 1 Copy To Appropriate District Office	State of New Me	xico		Form C-103
District I = (575) 393-6161	Energy, Minerals and Natu	ral Resources	[	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30 015 25141	r.T
District III – (505) 334-6178 1220 South St. Francis Dr.		icis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	54iii 10, 1111 0,	505	o. State Off & Gas	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Belco State	Ü
PROPOSALS.)  1. Type of Well: Oil Well Gas Well XX Other SWD		8. Well Number	#1 SWD	
2. Name of Operator			9. OGRID Numbe	·r
Basic Energy Services LP			246368	
3. Address of Operator P.O. Box 10460 Midland Texas 79702			10. Pool name or Wildcat  Delaware Brushy Canyon	
4. Well Location	·		<u> </u>	
Unit Letter <u>E</u> : 2200 feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line				
Section 20 Township 23 S Range 28 E NMPM County Eddy				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
				<u> </u>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE		<del></del>	P AND A	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN			. , , , , _	
DOWNHOLE COMMINGLE				
_				
OTHER: Run CIL Imag	е Туре	OTHER:	<del></del>	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Basic Energy Services L.P. respectfully submits the following plan to gather needed information to establish the condition the well bore and injection intervals.				
1. RU Wire Line Unit run sinker bar to btm tag fill.				
2. Displace 50 bbls of Xylene with 20 bbls of surfactant fresh H2O				
Allow solvent to work on casing walls for 24 hours shut in. SDFN				
3. Displace 50 bbls of 20% Mi-Cellular with 20bbls of surfactant fresh H2O allow to polish casing walls for 24 hours SDFN.				
4. Displace tbg. and casing with total 70 bbls of fresh water.				
<ol><li>MI RU logging trk. w/ lubri with Casing Inspection Ima</li></ol>	icator and boom truck, RIH with 1 ging Tool.	11/16" CIT to 382	24.45° and enter "F" i	nipple to 5815' log well
6. Report findings to Santa Fe	OCD EMNRD Phillip Goetze and	District II Richard	Inge.	
Spud Date:	Rig Release Da		8	
•				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE David H. Alvarado TITLE SENM District Fluids Mgr. DATE 10/12/15				
Type or print name David H. Alvarado  E-mail address: david.alvarado@basicenergyservices.com PHONE: 575, 746, 2072				
For State Use Only				
	1		Mai EA	510
APPROVED BY: DULAND   TITLE CONQUENCE OFFICER DATE 10/15/15  Conditions of Approval (if any):				