
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-26521
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. NM-4681
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPE	CICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name STATE 2
1. Type of Well: Oil Well X	Gas Well Other	8. Well Number 6
2. Name of Operator CHEVRON U.S.A. INC.	monty.mccarver@cjes.com	9. OGRID Number 4323
3. Address of Operator 1500 SMITH RD. MIDLAND, T.		10. Pool name or Wildcat SHUGART
	Y- LAT 32.68396 X-LONG -103.94591	
	660 feet from the SOUTH line and	1650 feet from the WEST line
Section 2	Township 19-S Range 30-E	NMPM County EDDY
	11. Elevation (Show whether DR, RKB, RT, GR,	
12. Check	Appropriate Box to Indicate Nature of Notice	ce, Report or Other Data
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	PLUG AND ABANDON X REMEDIAL W CHANGE PLANS ☐ COMMENCE MULTIPLE COMPL ☐ CASING/CEM	DRILLING OPNS. ☐ P AND A
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details	, and give pertinent dates, including estimated date
proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 13 3/8" 54# @ 667', TOC SURF. C SURF. PERFS 2,921'-2,958'.	
AS EARLY AS DECEMBER 7, 2	015 MOVE IN RIG & CMT EQUIPMENT, ND TR	EE, NU BOP & TEST. POOH TBG. & RODS
SET CIBP @ 2,900', RIH CIR W/	SALT GEL. MIX & SPOT 35 SX CL "C" CEMEN	T FROM 2,900'-2,600', WOC & TAG, TEST
MIX & SPOT 75 SX CL "C" CEM	ENT FROM 2,350'-1,750', WOC & TAG. (7 RIV	ERS, YATES, SHOE)
CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS	ENT FROM 750' BACK TO SURFACE. & REMOVED 3' BELOW GRADE. WELD ON D "C", W/ CLOSED LOOP SYSTEM USED.	RY HOLE MARKER. CLEAN LOCATION.
ul Bor must be Plug	of C-103 (Subseq	egging of well bore only. ond is retained pending receipt OIL CONSERVATION uent Report of Well Plugging) APTESIA DISTRICT
	which may be fou	and at OCD Web Page under
	Forms, www.cmm	rd.state.nm.us/ocd. NOV 1 8 2015
Spud Date:	Rig Release Date:	RECEIVED
I hander and first at the information	s above is two and complete to the best of my knowled	adas and halisf
Thereby certify that the information	above is true and complete to the best of my knowl	edge and benef.
SIGNATURE	TITLE_Agent for Chevron U	
Type or print haveMonty L. M For State Use Only APPROVED BY:	$\lambda = \lambda $	S.com PHONE: _713-325-6288 DATE 11/20/2015
Conditions of Approval (if any):	4500 Affected COA;	

CURRENT Chevron U.S.A. Inc. Wellbore Diagram: STATE 26




[Lease] OEU EUNICE FMT [Well No.] STATE 2 6 6 [Field] SHUGART
[Location] 660FSL1650FWL [Sec.] N/A [Blk] ______ [Survey] N/A
[County] Eddy [St.] New Mexico [Refno] OU9550 [API] 3001526521 [Cost Center] UCRJ11600
[Section] E030 [Township] 2 S [Range] S019 E
[Current Status] ACTIVE [Dead Man Anchors Test Date] 02/19/2013
[Directions] ______



P+A Chevron U.S.A. Inc. Wellbore Diagram: STATE 26



[Lease] OEU EUNICE FMT [Well No.] STATE 2 6 6 [Field] SHUGART
[Location] 660FSL1650FWL [Sec.] N/A [Bik] ______ [Survey] N/A
[County] Eddy [St.] New Mexico [Refno] OU9550 [API] 3001526521 [Cost Center] UCRJ11600
[Section] E030 [Township] 2 S [Range] S019 E
[Current Status] ACTIVE [Dead Man Anchors Test Date] 02/19/2013
[Directions] ______



Submix to Appropriate District Office State Lease — 6 copies Fee Lease — 5 copies DISTRICT I P.O. Box 1980, Hobbs, NM 88240

State of New Mexico Energy, Minerals and Natural Resources Department

CIST
Form C-105 Revised 1-1-89
Revises 1-1-89

DISTRICT II
P.O. Drawer DD. Artesia, NM 88210

OIL CONSERVATION DIVISION STATE OF THE PROPERTY OF THE PROPERT P.O. Box 2088

30-015-26521

Sama Fe, New Mexico 87504-2088	JAN 17 '91	STATE X	FEE [
	6. State Oil & Gas	esse No.	

Title Engr. Tech.

DISTRICT III

Signature Ken au Sosnell

1000 Rio Brazos Rd., A	ziec, NM 874	10						o d	Q. NM-	4681			
WELL C	OMPLETI	ON OR RE	COMPLE	TION REPO	RT A	ND LO	G AR	TESIA,	997//				
1a. Type of Well: OIL WELL X	_	VELL.	DRY 🗌							arme or i	Jait Agreen	ent Name	7111111
OIL WELL	y GAS	نے بادلات	DK1	OTHER	_				C+-	- - 2			
b. Type of Completion:	:	# 110						1	Sta	te 2			
WELL X OVER	Destro	EACE		RESVR OTHER	١								
2. Name of Operator			** **, **, **, **, **, **, **, **, **,	····					. Well N	λ		·	
ARCO OIL AN		DMPANY	<i></i>							6			
3. Address of Operator				·-				,	Pool me				
P. O. Box 1	.610, Mic	iland, T	exas 7	9702					Shug	art	Y-SR-	Q-G	
4. Well Location	27												
Unit Letter _	<u>N:</u>	66U Feet	Prom The	South		_ Line a	₩	1 <u>650</u>	Fo	st Proce T		est	Line
Section	2	Тенн	restrio 19	9S 1	Lange	30E		.	TA 4	r44			County
	11. Date T.D.		<u> </u>	engl. (Ready to P				NM		Eddy			
	11-24		i	15~90	roa.)			. 9 GI	RKB, RT	, GK, etc. 30 . 5		Elev. Cating	2680
15. Total Depth		g Back T.D.			mod. Ho				Rottry T			le Toots	
3200	1	3154		17. If Multiple Co Many Zoom?	7		Ď	servais rilled By	X		- [-		
19. Producing interval(s)	, of this compl	ation - Top, B	ottom, Name								us Direction	al Survey M	ade
2921-2958	Quee	n								N		•	
21. Type Electric and Ot									22. Was	Well Co	red		
FDC-CNL-G	R-Cal,	DLL-MS	FL-GR						N	0			
23.		CA	SING R	ECORD (R	eport	all stri	nes s	et in v	rell)				
CASING SIZE	WEIGH	T LB/FT.		H SET		E SIZE			ENTINO	RECO	RD	AMOUNT	PULLED
13 3/8	54		661	7	17	1/2			sx -				
8 5/8	24		1830			1/4			sx -	Cir	c		
5 1/2	15.	5	3200)		<u>7/8</u>		<u>550</u>	<u>sx -</u>	Cir	<u></u>		
	<u> </u>		<u> </u>	<u> </u>									
24.		ז ואו	ER RECO	אַר ייי			<u>.</u>	1 20		7 70 TAT	G RECOI	<u> </u>	
SEZE	TOP		TTOM	SACKS CEME	NT I	SCRE		25.	SIZE		DEPTH SE		KER SET
				0.000	-		<u> </u>	2	3/8	- - 	2999		-u
26. Perforation reco	ard (interval	, size, and n	iumber)		<u></u>							SQUEEZ	
2921-2958					-	DEPTH						MATERIAL	
					-	<u> 2921</u>	<u>-29</u>	58				Frac	
					┝╼	 -			!25,0	<u>uu g</u> i	ars &	63.00	10#sa.
28.				PRODUC	TION				<u>! — — </u>				
Date First Production		Productio	me Method (F	lowing, gas lift, p			i type p	нетр)		W	ell Status (Prod. or Sku	5-in)
12-15-90		pump	ing							_	Produ	ucina	
Date of Test	Hours Teste	xd C	hoke Size	Prod'n For	Oil	- Bbi.		Gas - MC	F	Water -	Bbi.		Oil Ratio
1-13-91	24	<u> </u>		Test Period		34		40		41		1176	
Flow Tubing Press.	Casing Pres		alculated 24- our flate		1	Gas - M		_	er - Bbl.	۲		API - (Con	''
	14			34		4	U	! 4	1	Milamore	37	. J	
29. Dispossion of Gas (Se	old, word for fi	et. Vertad, elc.	.;						Test	Witness	ю ву		ļ
sold 30 Lig Ameliments				·	<u></u>								
Electric	Ioas 1	Inclina	tion o	in ruov									ſ
31. I hereby certify that	the informa	tion shows of	n both sides	of this form is	true on	d comple	ete so s	he best o	f my lovo	wiedze a	nd belief		 j
	•					8-567				-	-		İ

Printed

Name

Ken W. Gosnell

INSTRUCTIONS

This form is to be filed with the appropriate District Office of the Division not later than 20 days after the completion of any newly-drilled or deepened well. It shall be accompanied by one copy of all electrical and radio-activity logs run on the well and a summary of all special tests conducted, including drill stem tests. All depths reported shall be measured depths. In the case of directionally drilled wells, true vertical depths shall also be reported. For multiple completions, Items 25 through 29 shall be reported for each zone. The form is to be filed in quintuplicate except on state land, where six copies are required. See Rule 1105.

INDICATE FORMATION TOPS IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE

So	utheastern N	New Mexico	Northwestern New Mexico					
T. Anhy	т	. Canyon	T. Ojo Alamo	T. Penn. "B"				
T. Salt	T		T. Kirtland-Fruitland					
B. Salt	Т	Atoica	T. Pictured Cliffs					
T. Yates 21	.36 τ	Miss	T. Cliff House	T. Leadville				
T. 7 Rivers22			T. Menefee	T. Madison				
T. Queen29	906т		T. Paint Lookout	T. Elbert				
			T. Mancos	T. McCracken				
T. San Andres	T		T. Gallup	T. Ignacio Otzte				
T. Glorieta				-				
			T. Dakota	T				
T. Blinebry	T	. Gr. Wash	T. Morrison	T				
			T. Todilto					
			T. Entrada	Т				
T. Abo	T		T. Wingate					
			T. Chinle					
T. Penn			T. Permain					
T. Cisco (Bough C)_	т		T. Penn "A"					
		OIL OR GAS SA	NDS OR ZONES					
No. 1, from		to	No. 3. from.	to				
No. 2. from		to	No. 4, from	to				
		IMPORTANT W						
Include data on rate	of water inflow	and elevation to which water rose	in hole.					
No. 1, from		to	feet					
No. 2, from		to	feet	************				
No. 3, from			f eet	• • • • • • • • • • • • • • • • • • • •				
	LITH	HOLOGY RECORD (A	ttach additional sheet if necessi	ary)				

From	То	Thickness in Feet	Lithology	From	То	Thickness in Feet	Lithology
0 720 830	720 1830 3200	1110	Surface Salt Anhy				

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:		URON	١.		
Well Name &	k Number:	علماك	2	# (e	
API #:	30)-015-2	62.	51	

- 1. Produced water will not be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- 12. 19.15.7.16: B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE: /1/20/20/5

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
 plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).