

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-015-30577
<b>1. Type of Well:</b> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> MARBOB ENERGY CORPORATION		<b>6. State Oil &amp; Gas Lease No.</b> 636
<b>3. Address of Operator</b> PO BOX 227, ARTESIA, NM 88211-0227		<b>7. Lease Name or Unit Agreement Name:</b> OXY MALT-O-MEAL STATE
<b>4. Well Location</b> Unit Letter <u>L</u> : 1800 feet from the <u>SOUTH</u> line and 660 feet from the <u>WEST</u> line Section <u>22</u> Township <u>17S</u> Range <u>28E</u> NMPM County <u>EDDY</u>		<b>8. Well No.</b> 1
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b> 3610' GL		<b>9. Pool name or Wildcat</b> EMPIRE; PENN

<b>11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</b>	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: WORKOVER <input checked="" type="checkbox"/>

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

TESTED MORROW SANDS AS FOLLOWS:

PERF MORROW ZONE @ 10003'-10005' (12). SET CIBP @ 10100'. PERF MORROW ZONE @ 10066'-10070' (16). SWAB. ACIDIZE W/ 250 GAL CLAY SAFE H ACID. SWAB. ACIDIZE PERFS 10003'-10005' W/ 250 GAL CLAY SAFE H ACID. SWAB. SET CIBP @ 9945'. WORKOVER UNSUCCESSFUL. NON-ECONOMIC PRODUCTION. WATER PRODUCTIVE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Cannon TITLE PRODUCTION ANALYST DATE 7/9/03

Type or print name DIANA J. CANNON

Telephone No. (505) 748-3303

(This space for State use)

APPROVED BY Jim W. Grew TITLE District Supervisor DATE JUL 11 2003

Conditions of approval, if any: