Form 3160-5 (

(June 2015)

NMOCD

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED

NMNM 36648

	pires: January 31, 201
5. Lease Serial No.	

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well.	Use Fòrm 3160-3 (A	PD) for such proposals	5.		•
SUBMIT IN	TRIPLICATE - Other instr	uctions on page 2		7. If Unit of CA/Ag	reement, Name and/or No.
1, Type of Well				· ·	
Oil Well 📝 Gas V	Well Other	,		8, Well Name and N	See Attached List
2. Name of Operator Vanguard Oper	ating, LLC			9. API Well No.	See Attached List
3a Address 5847 San Felip	e. Suite 3000	3b. Phone No. (include area cod	e)	10. Field and Pool o	r Exploratory Area
Houston, Texas		(832) 377-2243		,	See Attached List
4. Location of Well (Footage, Sec., T.,	R.,M., or Survey Description)			11. Country or Paris	sh, State
See Attached I	ist				CHAVES, NM
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOT	ICE, REPORT OR O	THER DATA
TYPE OF SUBMISSION		, TY	PE OF AC	TION	
Nacia estuana	Acidize	Deepen	Proc	luction (Start/Resume) Water Shut-Off
Notice of Intent	Alter Casing	Ilydraulic Fracturing	Rec	amation	Well Integrity
Zat in	Casing Repair	New Construction	Rec	omplete	✓ Other
✓ Subsequent Report	Change Plans	Plug and Abandon	=	porarily Abandon	
Final Abandonment Notice	Convert to Injection	= -	=	er Disposal	
13 D			A secondary		and the state of t

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfounded or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

This is notification of Change of Operator on the above referenced well. Vanguard Operating, LLC, as new operator, accepts all applicable terms, conditions, stipulations and restrictions concerning operations conducted on this lease or portion of lease described. Bond Coverage: BLM Bond File No. NMB000797, Surety Bond No. B006616 Bond Coverage Roswell Field Office: BLM Bond File No. NMB000857, Surety Bond No. B007133 Change of Operator Effective: October 5, 2015

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Accepted for record NACCD AB 5/85/16

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.	
/S/ DAVID R. GLASS	PETROLEUM ENGINEER Date MAR 2 5 2016
THE SPACE FOR FEDE	RAL OR STATE OFICE USE
Signature 2	Date 10.5. 2015
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Britt Pence	Executive Vice President, Operations Title

(Instructions on page 2)

Former Operator: LRE Operating LLC

ATTACHMENT TO LEASE SERIAL NO. NMNM 36648

我一只是我们的人的人的人的人,我们是我们的人的人的人的人的人的人的人的人的人的人的人的人的人的人的人的人的人的人的人	The first of the f	これのこのでは、これではないできる	1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			,	The state of the s	The state of the s	
WELLNAME	APINUMBER	EXPLORATORY, AREA	UNITLIR	SEC	Z	SEC TWN RNG	and the	LOCATION	
CHINA FEDERAL 1 30-005-1086 3 300056	300056	PECOS SLOPE; ABO, WEST	В	18	75	23€	23E 660 FNL	1980 FEL	
CHINA FEDERAL 11 30-005-01/68 300056	9 300056	PECOS SLOPE; ABO, WEST	8	20	75	23E	23E 660 FNL	2310 FEL	
CHINA FEDERAL 12 30-005- 6/659 300056	300056	PECOS SLOPE; ABO, WEST	E	19	75	23E	23E 1980 FNL	500 FWL	
CHINA FEDERAL 13 30.005. 6/688 300056	300056	PECOS SLOPE; ABO, WEST	٢	20	75	23E	23E 2310 FSL	990 FWL	
CHINA FEDERAL 14 30:005-6/649 300056	300056	PECOS SLOPE; ABO, WEST	_	19	75	23E	23E 2310 FSL 9	990 FEL	
CHINA FEDERAL 15 30-005-61670 300056	300056	PECOS SLOPE; ABO, WEST	κ	19	75	23E	23E 1444 FSL	1950 FWL	
CHINA FEDERAL 2 30-005-60868	300056	PECOS SLOPE; ABO, WEST	E	18	75	23E	23E 1800 FNL	660 FWL	
CHINA FEDERAL 3 30-005-1080	300056	PECOS SLOPE; ABO, WEST	E	17	75	23E	23E 1850 FNL	660 FWL	
CHINA FEDERAL 4 30005-101/17	300056	PECOS SLOPE; ABO, WEST	K	17	75	23E	23E 1650 FSL	1870 FWL	
CHINA FEDERAL 5 30-005- 11/105	300056	PECOS SLOPE; ABO, WEST	J	18	75	23E	23E 1322 FSL	2080 FEL	
CHINA FEDERAL 7 30-005-11/1/28	300056	PECOS SLOPE; ABO, WEST	K	18	7 S	23E	23E 1650 FSL	1875 FWL	
CHINA FEDERAL 8 30-005- 16/138	300056	PECOS SLOPE; ABO, WEST	A	19	75	23E	23E 660 FNL	560 FEL	
CHINA FEDERAL 9 30-005-11/457	300056	PECOS SLOPE; ABO, WEST	ш	20	75	23E	23E 1650 FNL	784 FWL	
		•							

Vanguard Operating, LLC Change of Operator Conditions of Approval

- 1. Tank battery must be bermed/diked (must be able to contain 1/1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days.
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.