| Submit 1 Copy To Appropriate District Office | State of New Mexico | Form C-103 |
|---|--|--|
| District 1 - (575) 393-6161 | Energy, Minerals and Natural Resources | Revised July 18, 2013 |
| 1625 N, French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 | OIL CONSERVATION DIVISION | WELL API NO. # 30 -005 - 60332 |
| 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 | 1220 South St. Francis Dr. | 5. Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 | Santa Fe, NM 87505 | STATE FEE 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM | | 315977 |
| 87505 SUNDRY NOT | ICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| DIFFERENT RESERVOIR. USE "APPLI | OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH | South Lucky lake Queen unit |
| PROPOSALS.) 1. Type of Well: Oil Well | Gas Well Other | 8. Well Number # / A |
| 2. Name of Operator Ban | V Bard LLC | 9. OGRID Number 371067 |
| 3 Address of Operator | Boy 4435 Rosnell MM 88202 | 10. Pool name or Wildcat Green |
| 4. Well Location Unit Letter 0: 660 feet from the South line and 1980 feet from the East line | | |
| Unit Letter : | Township 155 Range 29 E | 980 feet from the East line NMPM Chauscounty |
| Doction | 11. Elevation (Show whether DR, RKB, RT, GR, etc. | |
| | 3844' 6R | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | |
| | | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK TO PLUG AND ABANDON PREMEDIAL WORK TO ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A | | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB | | |
| - DÓWNHOLE COMMINGLE | Service Transfer | —., · \ |
| CLOSED-LOOP SYSTEM OTHER: 11 | OTHER: | : |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date | | |
| of starting any proposed w | ork). SEE RULE 19.15.7.14 NMAC. For Multiple Co completion. | mpletions: Attach wellbore diagram of |
| Du Tilles and loved Pocher not properly set. | | |
| 5-15-16 - PULL TURING and found Pacher not properly set. Put buil Plus on Turing Presenced UP good. Go back dound set new | | |
| Put buil Plus on IVBING Presence Dr 8000. | | |
| Pucher Present on cosing Hoded Present good at 400 PSI. | | |
| 6-16-16 Mr. Richard Inge, OCD complete preferred | | |
| Test and Passes | l, | NM OIL CONSERVATION ARTESIA DISTRICT |
| | | JUN 27 2016. |
| Spud Date: | Rig Release Date: | |
| opad Date. | rag release bate. | RECEIVED . |
| Thumber shorts, that the information | have in two and appellate to the best of my knowled | o and haliaf |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | |
| SIGNATURE ITA N/e/ | TITLE Duner | DATE 6-16-16 |
| The second section of the second second | | Q.Gmcd. con |
| Type or print name Steve // For State Use Only | CIG+ CC E-mail address: 6 Loken See | n Cattle Co. PHONE: 575-973-1346 |
| APPROVED BY: | | ist" DATE 6/28/16 |
| Conditions of Approval (if any): | , itte Color | DAIL VI- |