Form 3160-5 (August 2007)	UNITED STATES NM OIL CONSERVATION DEPARTMENT OF THE INTERIOR ARTESIA DISTRICT OCD Artesia							
SI				JUL 19	2016	5. Lease Serial No. NMNM05555443		
BUREAU OF LAND MANAGEMENT JUL 19 2016 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals RECEIVED					VED	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						7. If Unit or CA/Agreement, Name and/or No. 8910138100		
1. Type of Well					8. Well Name and No. ROSS DRAW 8			
2. Name of Operator Contact: ASHLEE FECHINO RKI EXPLORATION & PROD LLC E-Mail: ashlee.fechino@wpxenergy.com						9. API Well No. 30-015-23017-00-S1		
3a. Address3b. Phone No. (include area code)210 PARK AVE SUITE 900Ph: 970-404-5031OKLAHOMA CITY, OK 73102Ph: 970-404-5031					=)	10. Field and Pool, or Exploratory UNDESIGNATED		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish, and State		
Sec 27 T26S R30E SWNE 1650FNL 1650FEL					EDDY COUNTY, NM			
12. CHE	CK APPR	OPRIATE BOX(ES) TO	) INDICAT	E NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISS	SUBMISSION TYPE OF ACTION							
Notice of Intent		Acidize	🗖 De	epen	Product	ion (Start/Resume)	U Water Shut-Of	
_		Alter Casing	🗖 Fr	Fracture Treat		Reclamation		
Subsequent Report		Casing Repair	🖸 Ne	w Construction	🗖 Recomp	lete	Other	
Final Abandonment Notice	Notice	Change Plans	🗖 Ple	ig and Abandon	on 🔲 Temporarily Abandon		Change to Original A PD	
	1	Convert to Injection	🗖 Ph	ig Back	Water Disposal			
Ross Draw Unit #8. The well has been pe	erforated b	are in need of more tim	·		o moving			
Sundry is in response	•	•			SEE A	TTACHED FO		
		A		d For Rec	ord			
14. I hereby certify that the f	formaning is t	ma and compat	<u> </u>	MOCD		· · · · · · · · · · · · · · · · · · ·	<u> </u>	
· ·		Electronic Submission # For RKI EXPLO nitted to AFMSS for proc	341909 verifi RATION & Plessing by PF	ed by the BLM We ROD LLC, sent to RISCILLA PEREZ of	ell Informatior the Carlsbad on 06/14/2016	System		
	Name (Printed/Typed) ASHLEE FECHINO			Title REGULATORY SF				
Name (Printed/Typed) A								
	Electronic Su	ibmission)		Date 06/13/2	2016			
	Electronic Su	this space for	DR FEDER	A		SE		
	····		DR FEDER	A	OFFICE U		Date 07/11/	
Signature (I	NIMMER are attached. legal or equi	THIS SPACE FC	not warrant or	AL OR STATE	OFFICE U		Date 07/11/	

•

÷ •.

•

•

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Approved for a period of 1 year ending 7/11/2017 subject to conditions of approval. Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

-

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval <u>with wellbore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

## Ross Draw Unit 8

- 1. Well is approved to be SI for a period of 1 year or until 7/11/2017
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 7/11/2017
- 3. COA's met at this time.
- 4. This will be the last and only extension for this well.