Form 3160-5 (August 2007)

11

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD
Artesia

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRI NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
handoned wall. Hen form 3160-3 (APD) for each proposals	

٠	Lease Seriai No.	
	MultipleSee	Attached

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. MultipleSee Attached			
Name of Operator BURNETT OIL COMPANY IN	Contact:	LESLIE GA	RVIS	<u> </u>				
3a. Address 3b. Phone No. 801 CHERRY STREET UNIT 9 Ph. 817-50			o. (include area cod 83-8730	le)	10. Field and Pool, or Exploratory MultipleSee Attached			
FORT WORTH, TX 76102-66 4. Location of Well (Footage, Sec., 7		1)			11. County or Pari	sh. and Sta	te	
MultipleSee Attached					EDDY COUNTY, NM			
12. CHECK APP	ROPRIATE BOX(ES) TO) INDICATI	E NATURE OF	NOTICE, RE	PORT, OR OTH	HER DA	TA	
TYPE OF SUBMISSION	· .	•	ТҮРЕ С	OF ACTION				
Notice of Intent	☐ Acidize	□ Dec	epen	☐ Production	on (Start/Resume)	V	Vater Shut-Off	
_	☐ Alter Casing	🔲 Fra	cture Treat	☐ Reclamat	tion	_ v	Vell Integrity	
☐ Subsequent Report	☐ Casing Repair	□ Nev	w Construction	□ Recompl	ete		Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plu	g and Abandon	☐ Tempora	rily Abandon	Ven ng	iting and/or Flari	
•	Convert to Injection	njection Plug Back		isposal	8			
following completion of the involved testing has been completed. Final Al determined that the site is ready for f Burnett is requesting permissi We will only be flaring as need reported as per BLM requirem	bandonment Notices shall be fil- inal inspection.) ion to flare at the Jackson ded (i.e during DCP maint	ed only after all B 5 battery f	requirements, inclu	iding reclamation, th June 2016.	have been complete	ed, and the	operator has 04037	
We have previously received location and an updated batte	approval to install a flare a	at this are location i	s on file.				•	
The Jackson B5 battery is located at: T17S, R 30 E, SECTION 1, UNIT P, SESE							CONSERVATION ESIA DISTRICT	
1145' FSL, 1283' FEL LEASE: NMNM2747	· •					JUL 2	5 2016	
		Accept	ted For R	AB 1/2	27/10	REC	EIVED	
14. I hereby certify that the foregoing is	Electronic Submission #3 For BURNETT	OIL COMPAN	Y INC, sent to the	ne Carlsbad	•			
Name(Printed/Typed) LESLIE G	nmitted to AFMSS for proce SARVIS	essing by PRI		LATORY COO				
Signature (Electronic S	Submission)		Date 05/23/2	2016		•		
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	E			
Approved By DAVID R GLASS			TitlePETROLE	EUM ENGINE	======================================		Date 06/22/2016	
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent to condu- which would entitle the applicant to condu-	itable title to those rights in the		Office Carlsba	d				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #339941 that would not fit on the form

5. Lease Serial No., continued

NMLC055264 NMNM2747

Wells/Facilities, continued

Agreement NMNM2747	Lease NMNM2747	Well/Fac Name, Number JACKSON B 65	API Number 30-015-41191-00-S1
NMNM2747 NMNM2747 NMNM2747	NMNM2747 NMNM2747 NMNM2747	JACKSON B 17 JACKSON B 18 JACKSON B 33	30-015-04039-00-S1 30-015-04040-00-S1 30-015-23807-00-S1
NMNM2747	NMNM2747	JACKSON B 47	30-015-41399-00-S1
NMNM2747 NMNM2747	NMNM2747 NMNM2747	JACKSON B 5 JACKSON B 51	30-015-04037-00-S1 30-015-40139-00-S1
NMNM2747 NMNM2747	NMNM2747 NMNM2747	JACKSON B 53 JACKSON B 54	30-015-40942-00-S1 30-015-41190-00-S1
NMNM2747 NMNM2747	NMNM2747 NMNM2747	JACKSON B 57 JACKSON B 59	30-015-41003-00-S1 30-015-41278-00-S1
NMNM2747	NMNM2747	JACKSON B 63	30-015-41541-00-S1
NMNM2747	NMNM2747	JACKSON B 64	30-015-41277-00-\$1
NMLC055264	NMLC055264	JACKSON B 48	30-015-41540-00-S1
NMLC055264	NMLC055264	JACKSON B 50	30-015-39364-00-S1
NMLC055264	NMLC055264	JACKSON B 52	30-015-40558-00-S1
NMLC055264	NMLC055264	JACKSON B 55	30-015-40844-00-S1
NMLC055264	NMLC055264	JACKSON B 58	30-015-41192-00-S1
NMLC055264 '	NMLC055264	JACKSON B 60	30-015-41365-00-S1
NMLC055264	NMLC055264	JACKSON B 61	30-015-41542-00-S1
NMLC055264	NMLC055264	JACKSON B 62	30-015-41279-00-S1
NMLC055264	NMLC055264	GB JACKSON SA 38	30-015-04130-00-D2

Location
Sec 1 T17S R30E SESE 1190FSL 990FEL
Sec 1 T17S R30E SWSW 660FSL 660FWL
Sec 1 T17S R30E SWSW 660FSL 660FWL
Sec 1 T17S R30E SENW 1980FNL 2080FWL
Sec 1 T17S R30E SENW 1980FNL 2080FWL
Sec 1 T17S R30E SWSE 330FSL 1550FEL
32.857043 N Lat, 103.921318 W Lon
Sec 1 T17S R30E SWSW 990FSL 330FWL
Sec 1 T17S R30E SWSW 990FSL 330FWL
Sec 1 T17S R30E SWSW 990FSL 300FWL
Sec 1 T17S R30E SESW 990FSL 3100FWL
Sec 1 T17S R30E SESW 390FSL 1600FWL
Sec 1 T17S R30E SESW 390FSL 190FWL
32.857056 N Lat, 103.926335 W Lon
Sec 1 T17S R30E SESE 330FSL 480FEL
32.857034 N Lat, 103.917835 W Lon
Sec 1 T17S R30E NWSW 1650FSL 1070FWL
32.860694 N Lat, 103.92980 W Lon
Sec 1 T17S R30E NENE 330FNL 990FEL
32.855231 N Lat, 103.919644 W Lon Sec 12 T17S R30E NENE 330FNL 990FEL 32.855231 N Lat, 103.919644 W Lon Sec 12 T17S R30E NWSW 1650FNL 2310FEL Sec 12 T17S R30E NWSW 330FNL 2310FEL Sec 12 T17S R30E SWNE 2310FNL 1650FEL Sec 12 T17S R30E SWNE 990FNL 1650FEL Sec 12 T17S R30E SENE 1650FNL 990FEL 32.851597 N Lat, 103.919500 W Lon Sec 12 T17S R30E SENE 1650FNL 330FEL 32.84978 N Lat, 103.917503 W Lon Sec 12 T17S R30E NENE 290FNL 330FEL 32.853405 N Lat, 103.917350 W Lon Sec 12 T17S R30E NENE 660FNL 660FEL

10. Field and Pool, continued

GRAYBURG LOCO HILLS SQUARE LAKE UNKNOWN

32. Additional remarks, continued

The following wells are associated with this battery:

Jackson B /GJSAU 38 - 30-015-04130 Jackson B 17 - 30-015-04039 Jackson B 18 - 30-015-04040 Jackson B 33 - 30-015-23807

Jackson B 47 - 30-015-41399

Jackson B 48 - 30-015-41540

Jackson B 5 - 30-015-04037 Jackson B 50 - 30-015-39364

Jackson B 51 - 30-015-40139 Jackson B 52 - 30-015-40558 Jackson B 53 - 30-015-40942

Jackson B 54 - 30-015-41190 Jackson B 55 - 30-015-40844 Jackson B 57 - 30-015-41003

Jackson B 58 - 30-015-41192 Jackson B 59 - 30-015-41278 Jackson B 60 - 30-015-41365 Jackson B 61 - 30-015-41542 Jackson B 62 - 30-015-41279

Jackson B 63 - 30-015-41541 Jackson B 64 - 30-015-41277 Jackson B 65 - 30-015-41191

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene Carlsbad, New Mexico 88220-6292 (575) 234-5972 Venting and/or Flaring Conditions of Approval

This field office has evaluated the attached Notice of Intent as a request for flaring/venting beyond NTL-4A allowable thresholds (reasons, timeframes, and volumes), and has determined the following Conditions of Approval apply.

Conditions of Approval to Flare Gas

- 1. Comply with NTL-4A requirements
- Subject to like approval from NMOCD
- 3. Flared volumes are considered "avoidably lost" and will require payment of royalties. Volumes shall be reported on OGOR "B" reports as disposition code "08"
- 4. "Avoidably lost" flare volumes shall be metered due to their royalty bearing status. Install gas meter on vent/flare line to measure gas prior to venting/flaring operations if it is not equipped as such at this time.
- 5. Vent/flare gas metering to meet all requirements for a sales meter as per Federal Regulations, Onshore Order #5 and NTL 2008-01. Include meter serial number on sundry (form 3160-5).
- 6. This approval does not authorize any additional surface disturbance.
- 7. An updated facility diagram is required within 60 days of modifications to existing facilities per Onshore Order #3.
- 8. Approval not to exceed 90 days, if flaring is still required past 90 days submit new request for approval.
- 9. Submit Subsequent Report with actual volumes of gas flared for each month gas is flared on a sundry form 3160-5.

Definition: As per **NTL-4A II. A.** "Avoidably lost" production shall mean the venting or flaring of produced gas without the prior authorization, approval, ratification, or acceptance of the Supervisor and the loss of produced oil or gas when the Supervisor determines that such loss occurred as a result of (1) negligence on the part of the lessee or operator, or (2) the failure of the lessee or operator to take all reasonable measures to prevent and/or to control the loss, or (3) the failure of the lessee or operator to comply fully with the applicable lease terms and regulations, appropriate provisions of the approved operating plan, or the prior written orders of the Supervisor, or (4) and combination of the foregoing.

43CFR3162.7-1 (a) The operator shall put into marketable condition, if economically feasible, all oil, other hydrocarbons, gas and sulphur produced from the leased land.

43CFR3162.1 (a) The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. These include, but are not limited to, conducting all operations in a manner which ensures the proper handling, measurement, disposition, and site security of leasehold production; which protects other natural resources and environmental quality; which protects life and property; and which results in maximum ultimate economic recovery of oil and gas with minimum waste and with minimum adverse effect on ultimate recovery of other mineral resources.