Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			OMB	M APPROVED NO. 1004-0135		
			5. Lease Serial No.	s: July 31, 2010		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMNM035423	-	
				6. If Indian, Allottee	or tribe wame	
SUBMIT IN TR	IPLICATE - Other instruc	tions on rever	se side.	7. If Unit or CA/Ag	reement, Name and/or	
1. Type of Well ☐ Oil Well				8. Well Name and N ELIZANDO A FI		
2. Name of Operator Contact: DAVID STEWART OXY USA WTP LP E-Mail: david_stewart@oxy.com				9. API Well No. 30-015-21930		
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	3b. Phone No. (include area code) Ph: 432-685-5717			e) 10. Field and Pool, o LA HUERTA A	10. Field and Pool, or Exploratory LA HUERTA ATOKA (GAS)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State			
Sec 20 T21S R27E SESW 660FSL 1980FWL 32.459950 N Lat, 104.214220 W Lon				EDDY COUNT	EDDY COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TC	INDICATE N	ATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	(11 3183		ТҮРЕ С	DF ACTION		
□ Notice of Intent		🗖 Deeper		Production (Start/Resume)	U Water Shut-	
🛛 Subsequent Report	☐ Alter Casing ☐ Casing Repair	Fractur	e Treat onstruction	Reclamation Recomplete	Well Integrit Other	
Final Abandonment Notice	Change Plans	—	id Abandon	Temporarily Abandon		
_	Convert to Injection			U Water Disposal		
				He & tag cmt @		
6/28/2016 RIH to 10973' circ	hole w/ 10# MLE_M&P 30	sy CiH cm t Pi			30,00	
10720', PUH to 10243', M&P	30sx CL H cmt, PUH, WO	зх оптоніі, і і Э.	лі, чо о. к	In a lag chill the process	NNOB	
6/29/2016 RIH w/ tbg, no tag RIH to 10243', M&P 40sx CL cmt, PUH, WOC.	on plug @ 10243', POOH, H cmt, PUH, WOC. RIH 8	& LD 43 ceme tag cmt @ 999	nted jts, bad ' 90', PUH to 9	valve on pump truck, 957', M&P 30sx CL H	R.L.B.	
6/30/2016 RIH & tag cmt @ 9 PUH to 7354', M&P 75sx CL I	i692', PUH to 8748', M&P 3 H cmt, PUH, WOC.	30sx CL H cmt,	PUH, WOC.	RIH & tag cmt @ 8484', NM (
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission #3	A4276 vorified b		Il Information System		
	For OXY	USA WTP LP, s	ent to the Car	Isbad	RECEIVED	
Name (Printed/Typed) DAVID STEWART			itle SR. RE	EGULATORY ADVISOR		
a tt		D	ate 07/11/2	2016		
Signature (Electronic	······································				-	
a tt	Submission) THIS SPACE FO	R FEDERAL			-**	
Signature (Electronic)	······································	·	· · · ·	wals will	•* 	
a tt	THIS SPACE FO	not warrant or	<u>itle</u> Pe	OFFICE UP Inding BLM approvals will bsequently be reviewed nd scanned		

•

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #344276 that would not fit on the form

32. Additional remarks, continued

١

7/5/2016 RIH & tag cmt @ 6642', POOH. RIH & set pkr @ 4523'. RIH & perf @ 5060', EIR @ 2bpm @ 500#, no returns, M&P 50sx CL C cmt, WOC.

7/6/2016 RIH & tag cmt @ 4800', PUH & set pkr @ 2375'. RIH & perf @ 3050', EIR @ 2bpm w/ full returns up 5-1/2" X 8-5/8", M&P 100sx CL C cmt w/ 2% CaCl2, WOC. RIH & tag cmt @ 2730', POOH. Pkr wouldn't release, RIH w/ WL & perf tbg @ 2368', circ up 5-1/2" @ 1bpm @ 0#. Contact Chris Walls-BLM, rec appr to cut tbg & lease pkr in hole. RIH w/ free point & jet cutter, cut tbg @ 2370', POOH. RIH & set pkr @ 1599', RIH & perf @ 1845', EIR @ 2bpm w/ full returns up 5-1/2" X 8-5/8", M&P 50sx CL C cmt w/ 2% CaCl2, POOH, WOC.

7/7/2016 RIH & tag cmt @ 1597', POOH. RIH & perf @ 650', EIR up 5-1/2" X 8-5/8" & no returns up 8-5/8" & 13-3/8", PUH & perf @ 60', EIR w/ full returns up 5-1/2" X 8-5/8" & 8-5/8" X 13-3/8", ND BOP, NU WH & Adapter, M&P 170sx CL C cmt, circ cmt to surf on 5-1/2", 5-1/2" X 8-5/8" & 8-5/8" X 13-3/8", 13-3/8", visually confirmed. RDPU.