Form 3160-5 (August 2007)

UNITED STATES

APTERIA OF THE UNITED STATES ARTESIA DISTRICT
DEPARTMENT OF THE INTERIOR OCD Artesia
BUREAU OF LAND MANAGEMENT 1 7 2016

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

NMNM-025503

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to be be being an abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

abandoned well.	USE FORM 3160-3 (A	(PD) for such propose	a <i>is.</i>	<u> </u>	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well				- NM 88499X	
Oil Well Gas Well Other INJECTION				8. Well Name and No. BENSON SHUGART WFU # 11	
2. Name of Operator CHEVRON U.S.A. INC.				9. API Well No. 30-015-20528	
3a. Address	3b. Phone No. (include area o	. Phone No. (include area code)		10. Field and Pool or Exploratory Area	
DEAUVILLEE BLVD. ROOM #N3002 MIDLAND, TX. 79706	432-687-7279 LEE ROAK		SHUGART		
4. Location of Well (Footage, Sec., T.,)		11. Country or Parish, State		
2,310' FSL & 330' FEL, SEC-26, T- 18S, R-30E, MER NMP				EDDY CO, NM.	
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NATU	RE OF NOTIC	CE, REPORT OR OTH	IÈR DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Prod	luction (Start/Resume) Water Shut-Off	
	Alter Casing	Fracture Treat	Recla	amation Well Integrity	
Subsequent Report	Casing Repair	New Construction	Reco	omplete Other	
	Change Plans	Plug and Abandon	_	porarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back		ter Disposal	
Attach the Bond under which the violation of the involvesting has been completed. Final determined that the site is ready for 129 / 16 MI & RU, RDWH, NU B 07 /30 / 16 MIX & SPOT 148 SX CL PERF @ 760', MIX & SQZ 85 SX C 07 / 31 / 16 PERF @ 415' & 40', UN MIX & SPOT 36 SX CL "C" CMT FF 08 / 01 / 16 PERF & CIR 55 SX CL CUT OFF WELL HEAD 3' BGL, INSCLASS " C " CEMENT USED W/ C BOND COVERAGE: CA 0329	red operations. If the operation Abandonment Notices must refinal inspection.) OP's, TEST, RIH TO 2,970'- "C" CMT FROM 2,970'- L"C" CMT FROM 760'-45 IABLE TO CIR. PERF @ 3 ROM 438'-80' PU & SQZ 3 "C" CMT FROM 90' TO SI STALL REQUIRED DRY H	on results in a multiple complet be filed only after all requirement of & TAG CIBP @ 2,970', CII 1,530', WOC TAG 1,536', JII 0'. WOC & TAG 438' 335', 140' & 50' STILL UNAB WA BBL ISIP 1,100 PSI. URFACE ON BOTH STRING OLE MARKER AS PER CO.	tion or recompents, including R MLF. M AMOS W/ LE TO CIR. I	netion in a new interval reclamation, have been not been	I, a Form 3160-4 must be filed once in completed and the operator has EPTH. M BLM OK TO SPOT PLUG. TION. To plugging of the well bore, ler bond is retained until operator is completed.
14. I hereby certify that the foregoing is t	rue and correct. Name (Printe	d/Typed)		-onted t	Oktoo was a second of the contract of the cont
Monty L. McCarver	2	Title SR. Ma	anager / Age	ntier Chervon INA) Fic }
Signature		Date 08/03/	2016	Ř.L	, B,
Accepted For Record	THIS SPACE	FOR FEDERAL OR S	TATE OF	FICE USE	
Approved by conditions of approval, if any, are attached that the applicant holds legal or equitable the entitle the applicant to conduct operations	itle to those rights in the subje	Title s not warrant or certify ct lease which would Office	SPET	7	Date 8-9-/C
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a		and willfully t	o make to any departmen	nt or agency of the United States any false,
fictitious or fraudulent statements or repre	sentations as to any matter wi	thin its jurisdiction.			
(Instructions on page 2)					