

In Reply Refer to 3162.4 (P0220)

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene Carlsbad, New Mexico 88220-6292 www.nm.blm.gov

AUG 1 6 2016



OXY USA Inc 5 Greenway Plaza, STE 110

Houston, TX 77046-0521



AUG 22 2016



RECEIVED

Gentlemen:

Your Application for Permit to Drill (APD) for the well listed below has expired because drilling has not commenced per Onshore Order #1:

<u>LEASE</u>	WELL NAME AND LOCATION	EXPIRATION
NM15003	Government AB Fed - 15 30-015-4/6/2	August 14, 2016
	2020' FSL & 660' FWL, sec. 10, T. 20 S., R. 28 E. Government AB Fed – 16 30-0/5-4/6/3	August 14, 2016
	2060' FSL & 1980' FEL, sec. 10, T. 20 S., R. 28 E.	7146451 11, 2010

If the well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this wells at a later date, please submit a complete application (1 original and 3 copies) to this office. Since the original APD has expired, the resubmitted APD will be subject to all processing requirements including the \$6,500 application fee and the 30-day posting period. Please note on the resubmitted APD that it was previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Jim Amos at (575) 234-5909.

Sincerely,

/s/ JD Whitlock Jr

Cody Layton Assistant Field Manager, Lands & Minerals