Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-013
Expires: July 31, 201

SUNDRY Do not use th	Lease Serial No.     NMNM13996     If Indian, Allottee or Tribe Name							
abandoned we								
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well	8. Well Name and No. CEDAR CANYON 22 FEDERAL COM 6H							
2. Name of Operator OXY USA INC.		9. API Well No. 30-015-43759						
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	3b. Phone No. (includ Ph: 432-685-571				Exploratory V BONE SPRING			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)		11. County or Parish, and State					
Sec 22 T24S R29E SWSW 10 32.198466 N Lat, 103.979724		EDDY COUN			, NM			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION		TYPE OF ACTION						
☑ Notice of Intent	☐ Acidize	dize Deepen Production (Start/Resur		on (Start/Resume)	☐ Water Shut-Off			
_	☐ Alter Casing	☐ Fracture Tr	eat	■ Reclamation		■ Well Integrity		
☐ Subsequent Report ☐ Casing Repair		☐ New Construction [		☐ Recomp	lete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and A	bandon	□ Temporarily Abandon				
	☐ Convert to Injection	☐ Plug Back	□ Water Disposal					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  OXY USA Inc. respectfully requests to skid the Cedar Canyon 22 Federal Com #6H, API No. 30-015-43759 20' south of the original location, due to being unable to fish out the BHA. This well was plugged per the BLM recommendations. Please see attached for a 3160-3 with the required attachments for the Cedar Canyon 22 Federal Com #6HY replacement well. No additional surface disturbance will be required.								
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #350521 verified by the BLM Well Information System  For OXY USA INC., sent to the Carlsbad								
Name (Printed/Typed) DAVID STEWART			SR. REC	REGULATORY ADVISOR				
Signature (Electronic	Submission)	Date	09/08/20					
THIS SPACE FOR FEDERAL OR STATE OFFICE  Pending BLM approvals will								
Approved By	ubject lease Offic	su e a	nd scanne	approvais y be reviewed d	agency of the United			