Form 3160-5 (April 2004)

OCD-ARTESIA UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED	
OM B No. 1004-0137	
Expires: March 31, 2007	

5. Lease Serial No. NMLC028731B

5.	lf	Indian,	Allottee	or Tribe	Name
----	----	---------	----------	----------	------

abandoned wei	l. Use Form 3160 - 3 (A	NPD) for such p	proposals.				
	PLICATE- Other instr	uctions on rev	erse side. RECEIVED	7. If Unit or (A/Agreement, Name and/or No.		
1. Type of Well Oil Well			8. Well Nam	1			
2. Name of Operator Marbob Energ	gy Corporation	Q	CU-AMIESIA	9. API Well	deral Unit #6 WIW I No.		
3a. Address PO Box 227, Artesia, NM 8821	1-0227	3b. Phone No. (include area code) 505-748-3303		30-015-20165			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area Grbg Jackson SR Q Grbg SA			
1980 FNL 660 FEL, Sec. 10-T17	7S-R29E, Unit H			11. County or Eddy Co	Parish, State		
12. CHECK API	PROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NOTICE, R	EPORT, OR	OTHER DATA		
TYPE OF SUBMISSION		Т	YPE OF ACTION				
Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Subsequent Report New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed we				andon y proposed work	Water Shut-Off Well Integrity Other and approximate duration thereof.		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Marbob Energy Corporation proposes to plug & abandon as follows: Notify BLM 24 hrs before starting plugging. 1. POOH w/ pkr. Set 4 1/2" CIBP @ 2320' (Perfs @ 2406' - 2436'). Cap w/ 35' cmt. 2. Spot 100' plug @ 2093'. 3. Spot 100' plug @ 1819'. 4. Perf sqz 100' plug @ 573' (8 5/8" shoe @ 523'). WOC. Tag. 5. Perf @ 60'. Circ cmt to surface.							
6. Cut off wellhead. Install			APPROVAL S GENERAL RI SPECIAL ST	EQUIREM			
14. I hereby certify that the foregon Name (Printed/Typed)	oing is true and correct						
Diana J. Briggs	,	Title	Production Analyst				
Signature	Dugos	Date	03	3/10/2006			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by ORIG. SGL).) ALEXIS C. SWOBOL	DA PE	TROLEUW EN	GWEER Dat	MAR 1 6 2006		
Conditions of approval, if any, are att certify that the applicant holds legal o which would entitle the applicant to c	r equitable title to those rights in onduct operations thereon.	the subject lease	Office				
Title 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or fraudulen	3 U.S.C. Section 1212, make it a t statements or representations as	crime for any person to anymatter within	knowingly and willfully to its jurisdiction.	make to any d	epartment or agency of the United		