Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BURFALLOF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

σ,	LIDEALLOET AND MANACEN	MENT	Ехриса	. January 31, 2016	
BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			5. Lease Serial No. NMNM15311		
			6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well		8. Well Name and No. EL PASO 23 FED 1			
Oil Well Gas Well Other  2. Name of Operator Contact: STAN WAGNER				9. API Well No.	
EOG RESOURCES, INC.  E-Mail: stan_wagner@eogresources.com				30-015-24039	
3a. Address ATTN: STAN WAGNER P.O. MIDLAND, TX 79702		o. Phone No. (include area code) h: 432-686-3689	10. Field and Pool ROSS DRAW	10. Field and Pool or Exploratory Area ROSS DRAW WOLFCAMP	
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description)		11. County or Parish, State		
Sec 23 T26S R30E Mer NMP	660FSL 660FWL		EDDY COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	Convert to Injection	☐ Plug Back	☐ Water Disposal		
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for following that the site is ready for following that the site is ready for following the site is ready for following that the site is ready for following the site is ready for following the site is ready for following the site is ready	d operations. If the operation results bandonment Notices must be filed of final inspection.  4-1/2" CIBP at 11800'. Dump t 11745'. Spot 25 sx Class H t 11308'. sing at 10720'. Packer at 1030'. cement plug 10770' to 10370' t 10448'. sing at 9062'. and squeeze 50 sx Class H t 8855'. Perforate 4-1/2" casi at 7458' to 7279'. t 7256'. Perforate 4-1/2" casi	in a multiple completion or reconly after all requirements, including the bailed 35' cement cap. cement 11745' to 11530'. Note that the bailed 35' cement 11745' to 11530'. Note that the bailed 35'. WOC.  Cement, displace to 8850'. ing at 7458'.	woc.	3160-4 must be filed once ed and the operator has	
14. I hereby certify that the foregoing is  Name (Printed/Typed) STAN WA	Electronic Submission #3639 For EOG RESO Committed to AFMSS for proc	DURCES, INC., sent to the Co cessing by DEBORAH MCKII	Information System arisbad NNEY on 01/24/2017 () ATORY ANALYST	ed for record	
Signature (Electronic	Submission)	Date 01/17/20	917 69	ed ico	
Secrepted for Record	THIS SPACE FOR	FEDERAL OR STATE (	OFFICE USE	R. Lev	
Approved By James	a. amos	Title SA	§7	72-3-17 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in the sub	warrant or ject lease Office	)		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #363993 that would not fit on the form

## 32. Additional remarks, continued

Pump 25 sx Class C cement 3664' to 3500'. WOC.
12/16/16 RIH and tag TOC at 3489'. Perforate 4-1/2" casing at 1460'.
Squeeze 50 sx Class C cement 1460' to 1350'. WOC. RIH and tag TOC at 1345'.
Perforate 4-1/2" casing at 396'. Circulate cement to surface. WOC. Tag TOC at surface.
12/19/16 Cut off wellhead and install below ground P&A marker.