Submit 1 Copy To Appropriate District State of New Mexico Office NM OIL CONSERVEY, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
District I – (575) 393-6161 AFTESIA DISTRICT 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II $-15/5$ $740-1205$ $1.1$	30-015-29583
811 S. First St., Artesia, NM 88210FED Z 2011 CONSERVATION DIVISIONDistrict III - (505) 334-61781220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505	STATE     FEE       6. State Oil & Gas Lease No.
$\frac{\text{District IV}}{1220 \text{ S. St. Francis Dr., Santa Fe, NM 87505}}$ Santa Fe, NM 87505 $\frac{\text{RECEIVED}}{1220 \text{ S. St. Francis Dr., Santa Fe, NM 87505}}$	0. State Off & Cas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	BERETTA 15 STATE COM
1. Type of Well: Oil Well 🔲 Gas Well 🛛 <u>Other</u>	8. Well Number 2
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, LP	6137 10. Pool name or Wildcat
3. Address of Operator 333 W. Sheridan Avenue, Oklahoma City, OK 73102	Carlsbad;Morrow, South (Gas)
4. Well Location	
Unit Letter _ G : 2180 feet from the North line and _ 1980 feet from the East line	
Section 15 Township 23S Range 26E	NMPM Eddy County, NM
11. Elevation (Show whether DR, RKB, RT, GR, etc	
3335' KB; 3317' GL; 18' KB to GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING  CEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PAND A	
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEMENT JOB	
	_
OTHER: OTHER: OTHER: OTHER:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
1. 2/6/17MIRU P&A unit and equipment.	
2. Unable to retrieve 2-3/8" production tubing and packer @ 11,458'. Cut tubing and POOH W/tubing from 11,450'.	
<ol> <li>Set a 4-1/2" CIBP @ 11,448'. Circulate with 10# mud.</li> <li>Spot 70 sx Cl H @ 11,448'. Tagged TOC @ 10,677'. Test casing to 1500 psi. Held Ok.</li> </ol>	
5. Perfed 7" casing @ 8,680'. Pumped 50 sx Cl H in/out @ 8,680'. Tagged TOC @ 8,531'. (T.Wolfcamp @ 8,682')	
6. Perfed 7" casing @ 5,540'. Pumped 120 sx Cl C in/out @ 5,540'. Tagged TOC @ 5,090'.(3000' spacer @ 5540'; T.BS @	
5200')	
<ol> <li>Perfed 7" casing @ 2,740'. Pumped 40 sx Cl C in/out @ 2,740'. Tagged TOC @</li> <li>Perfed 7" casing @ 1,945'. Pumped 155 sx Cl C in/out @ 1,945'. Tagged TOC @</li> </ol>	
1 506')	
9. Perfed 7" casing @ 715'. Pumped 50 sx Cl C in/out @ 715'. Tagged TOC @ 520'. (T.Salt @ 716')	
10. Perfed 7" casing @ 140'. Pumped 40 sx Cl C in/out to surface.	
11. 2/1//1/Cut weinlead on 4 BOL. Set above ground dry note marker. Wendore plugged & abandoned, wein a per marker	
Spud Date: Rig Release Date:	dir russing sport Web Ver
	Aperove under and to and the
Lharshy sartify that the information shows is true and complete to the heat of my knowledge and Nieds and Nieds	
Thereby certify that the information above is the and complete to the best of my knowledge and hence.	
SIGNATURE KEMMA Stark TITLE Production Technolog	istDATEDATE
<ul> <li>9. Perfed 7" casing @ 715'. Pumped 50 sx Cl C in/out @ 715'. Tagged TOC @ 520'. (T.Salt @ 716')</li> <li>10. Perfed 7" casing @ 140'. Pumped 40 sx Cl C in/out to surface.</li> <li>11. 2/17/17Cut wellhead off 4' BGL. Set above ground dry hole marker. Wellbore plugged &amp; abandoned, will pore only receipted to the process of the proces of the process of the</li></ul>	
APPROVED BY: Mainting TITLE COMPLIANCE OFFICER DATE 2/22/17	

Conditions of Approval (if any):

é