Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

OCD Artesia

ומ	LIDEATION LAND MANA	CENTENIE			Exputes, Jai	Huary 31, 2010	
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM0405444		
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. TODD 23 FED 4		
Name of Operator Contact: LINDA GOOD DEVON ENERGY PRODUCTION CO EMail: linda.good@dvn.com					9. API Well No. 30-015-26928-00-S1		
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102		3b. Phone No. (include area code) Ph: 405-552-6558			10. Field and Pool or Exploratory Area SAND DUNES		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 23 T23S R31E NESE 1800FSL 900FEL					EDDY COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDIC	ATE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent	☐ Acidize	D D	eepen	☐ Product	tion (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	□ H	☐ Hydraulic Fracturing ☐ Reclam		ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair		☐ New Construction ☐ I		olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ P	☐ Plug and Abandon 🛮 🗷 Tem		rarily Abandon		
	☐ Convert to Injection	□ P	☐ Plug Back ☐ Wat		Disposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f Devon Energy Production Corecompletion.	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation re boundonment Notices must be fil inal inspection.	give subsurfa the Bond No sults in a mult ed only after a	ce locations and measu on file with BLM/BIA tiple completion or reco all requirements, includ-	red and true von Required sumpletion in a ing reclamation	ertical depths of all pertin bsequent reports must be new interval, a Form 316 m, have been completed a	ent markers and zones. filed within 30 days 0-4 must be filed once	
NM OIL CONSERVATION ARTESIA DISTRICT					NMI 2	OCD RI 12817	
	FEE 22 2017	SEE	ATTACHED F	FOR	(12917	
	RECEIVED	CON	DITIONS OF	APPRO	JVAL		
14. I hereby certify that the foregoing is	Electronic Submission # For DEVON ENERG	SY PRODUC	TION CO LP, sent t	o the Carlst	pad		
Committed to AFMSS for processing by DEBO Name (Printed/Typed) LINDA GOOD			1	·			
Signature (Electronic S	Submission)	<u> </u>	Date 08/29/20	016			
	THIS SPACE FO	R FEDER	RAL OR STATE	OFFICE U	SE		
Approved By CHARLES NIMMER			TitlePETROLE	UM ENGIN	EER	Date 02/15/2017	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				i			
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any	person knowingly and	willfully to m	ake to any department or	agency of the United	

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

TODD 23I FEDERAL 4

- 1. Well is approved to be TA/SI for a period of 12 months or until 2/15/2018
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 2/15/2018
- 3. COA's met at this time.