Tuesday, March 28, 2006

30-005-63505-00-00 RANDALL FEE

## Well Selection Criteria Quick Print

(tblWellMaster.api\_wellno Like '30005635050000')

API Well #

Well Name and No.

Operator Name ELK OIL CO

001

Typ Stat County

A Chaves

Surf

**Twp** 10 S Rng Ft N/S Ft E/W UICPrmt
27 E 1650 S 330 E

Lst Insp 4/22/2005

Page 1

Please do final P.A. inspection on this well.

DA OK TO Release
3/30/06

30.005-63505

Submit 3 Copies to Appropriate District Office

TYPE OR PRINT

APPROVED BY

(This space for State Use)

CONDITIONS OF APPROV

## State of New Mexico

Jos**é**phij. Kelly

TITLE

Form C-103

TELEPHONE NO.

DATE

505-623-3190

MAR 3 1 2006

Energy, Minerals and Natural Resources Department Revised 1-1-89 **OIL CONSERVATION DIVISION** DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 2040 South Pacheco WELL API NO. 30-005-63505 Santa Fe, New Mexico 87505 5. Indicate Type of Lease STATE FEE 1301 W. Grand Ave., Artesia, NM 88210 RECEIVED 6. State Oil & Gas Lease No DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 MAR 2 4 200F SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO . Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) . Type of Well OTHER RANDALL FEE WELL X WELL 8. Well No. Name of Operator **ELK OIL COMPANY** 9. Pool Name or Wildcat 3. Address of Operator POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310 WILDCAT 4 Well Location EAST Line 1650 SOUTH 330 Unit Letter Feet From The Line and Feet From The 10 SOUTH 27 EAST **CHAVES** Section NMPM County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3717' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER OTHER: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) Plug and Abandon Well as Follows: 04/19/05 SET CIBP @ 6800' - DUMP 35' CEMENT ON TOP 04/20/05 SPOT 25 SXS @ 4800' - 4550' 04/20/05 PULL 3570' OF 5 1/2" CASING 04/21/05 SPOT 45 SXS @ 3620' - 3516' & TAG 04/22/05 SPOT 45 SXS @ 1650' - 1517' TAG 04/22/05 SPOT 35 SXS @ 350' - 224' & TAG 04/25/05 SPOT 10 SXS @ 30' TO SURFACE **INSTALL DRY HOLE MARKER** CIRCULATE 10# MUD LOCATION HAS BEEN CLEANED AND LEVELLED. READY FOR INSPECTION. I hereby certify that the information above is to ue and complete to the best of my knowledge and belief. 03/22/06 SIGNATURE ~ **PRESIDENT** DATE