Dilice   1-(375)-39-3-616   Not   Olic Consistent Articles   District   1-(375)-38-128   Not   1-(375)-38-128
Destret   - (37) As   - (38)   As   - (38)   Apr   1   CONSERVATION DIVISION   SILS fras   Arisis, Nasis,
1000 Rb Brazos Rd, Azec, NM 87410   Santa Fe, NM 87505   Santa Fe, NM 87505   Sut Francis Dr., Santa Fe, N
Santa Fc, NM 87505  Sundar Fc, NM 87506  Sundar Fc, NM 88 Lt.  Sundar Fc, NM 88 Lt.  Sundar Fc, NM 87506  Sundar Fc, NM 88 Lt.  Sundar Fc, NM
SUNDRY NOTICES AND REPORTS ON WELLS  DONOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPER OR PLUG BACK TO A DIFFERENT REESER VOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.]  1. Type of Well: Oil Well
SUNDRY NOTICES AND REPORTS ON WELLS   7. Lease Name or Unit Agreement Name   DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH   8. Well Number   S.
DIFFERINT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)   1. Type of Well: Oil Well
PROPOSALS   1. Type of Well: Oil Well
2. Name of Operator EOG Y Resources, Inc. 3. Address of Operator 104 South Fourth Street, Artesia, NM 88210  4. Well Location Unit Letter C: 330 feet from the North line and 2310 feet from the West line Section 2 Township 22S Range 31E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3514'GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   CHANGE PLANS   SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK   PAND A MULTIPLE COMPL   COMMENCE DRILLING OPNS   PAND A M
BOG Y Resources, Inc.
Lost Tank; Delaware
4. Well Location Unit Letter C : 330 feet from the North line and 2310 feet from the West line Section 2 Township 22S Range 31E NMPM Eddy County  11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3514*GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ CHANGE PLANS □ CHANGE PLANS □ CHANGE PLANS □ CHANGE PLANS □ CHANGE DELLING OPNS.□ PAND A ☑ CHANGE PLANS □ CHANGE DELLING OPNS.□ PAND A ☑ CHANGE PLANS □ CHANGE DELLING OPNS.□ PAND A ☑ CHANGE PLANS □ CHANGE DELLING OPNS.□ PAND A ☑ CHANGE DELLING OPNS.□ PAND A ☐ CHANGE D
Unit Letter C : 330 feet from the North line and 2310 feet from the West line Section 2 Township 228 Range 31E NMPM Eddy County  11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3514'GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   COMMENCE DRILLING OPNS.   P AND A LITER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   CASING/CEMENT JOB   OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  3/27/17 - MIRU. Loaded and tested to 500 psi, held ok. 3/28/17 - ND wellhead and NU BOP. 3/3/17 - Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/3/17 - Tagged TOC at 6640', Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 - Tagged TOC at 405'. Perforated at 4100'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 405'-708' calc TOC. 4/6/17 - Tagged TOC at 4737'. ND BOP. Spotted 15 sx Class "C" cement from 407'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 - Tagged TOC at 4737'. ND BOP. Spotted 15 sx Class "C" cement from 107'-3910' calc TOC. Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3514'GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   COMMENCE DRILLING OPNS.   P AND A   CASING/CEMENT JOB    PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  3/27/17 MIRU. Loaded and tested to 500 psi, held ok. 3/28/17 ND wellhead and NU BOP. 3/31/17 Pounded 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/5/17 Tagged TOC at 400'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 4100'. 4/5/17 Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 Tagged TOC at 4010'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 - Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data    NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:    SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PAND A PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   PAND A DOWNHOLE COMMINGLE   CLOSED-LOOP SYSTEM   OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  3/27/17 — MIRU. Loaded and tested to 500 psi, held ok. 3/28/17 — ND wellhead and NU BOP. 3/29/17 — Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 — Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'. 4/3/17 — Tagged TOC at 4640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 — Tagged TOC at 4103'. Perforated at 4100'. 4/5/17 — Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 — Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 — Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PAND A  DOWNHOLE COMMINGLE  CLOSED-LOOP SYSTEM  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  3/27/17 — MIRU. Loaded and tested to 500 psi, held ok. 3/28/17 — ND wellhead and NU BOP. 3/29/17 — Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 — Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 — Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 — Tagged TOC at 4105'. Perforated at 4100'. 4/5/17 — Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 — Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 — Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
TEMPORARILY ABANDON
PULL OR ALTER CASING
DOWNHOLE COMMINGLE  CLOSED-LOOP SYSTEM  OTHER:  OTHER:
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  3/27/17 — MIRU. Loaded and tested to 500 psi, held ok. 3/28/17 — ND wellhead and NU BOP. 3/29/17 — Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 — Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'. 4/3/17 — Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 — Tagged TOC at 4105'. Perforated at 4100'. 4/5/17 — Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 — Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 — Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>3/27/17 – MIRU. Loaded and tested to 500 psi, held ok.</li> <li>3/28/17 – ND wellhead and NU BOP.</li> <li>3/29/17 – Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP.</li> <li>3/31/17 – Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'.</li> <li>4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC.</li> <li>4/4/17 – Tagged TOC at 4105'. Perforated at 4100'.</li> <li>4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC.</li> <li>4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing.</li> <li>4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.</li> </ol>
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  3/27/17 – MIRU. Loaded and tested to 500 psi, held ok. 3/28/17 – ND wellhead and NU BOP. 3/29/17 – Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 – Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'. 4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 – Tagged TOC at 4105'. Perforated at 4100'. 4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
3/28/17 – ND wellhead and NU BOP. 3/29/17 – Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 – Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'. 4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 – Tagged TOC at 4105'. Perforated at 4100'. 4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
3/28/17 – ND wellhead and NU BOP. 3/29/17 – Spotted 25 sx Class "H" cement from 8214'-8016' Calc TOC. RIH with GR/JB to 6898'. Set a 5-1/2" CIBP at 6898'. Tagged CIBP. 3/31/17 – Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'. 4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 – Tagged TOC at 4105'. Perforated at 4100'. 4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
CIBP.  3/31/17 – Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'.  4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC.  4/4/17 – Tagged TOC at 4105'. Perforated at 4100'.  4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC.  4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing.  4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
3/31/17 – Pumped 70 bbls MLF. Tested casing to 500 psi. Spotted 25 sx Class "C" cement on top of CIBP. Calc TOC at 6643'.  4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC.  4/4/17 – Tagged TOC at 4105'. Perforated at 4100'.  4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC.  4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing.  4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
4/3/17 – Tagged TOC at 6640'. Perforated at 4354'. Pumped 35 sx Class "C" cement from 4354'-4164' calc TOC. 4/4/17 – Tagged TOC at 4105'. Perforated at 4100'. 4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
4/5/17 – Could not establish a rate. Tagged TOC at 4107'. Spotted 20 sx Class "C" cement from 4107'-3910' calc TOC. WOC. Tagged TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
TOC at 3936'. Perforated at 850'. Could not establish a rate. Spotted 20 sx Class "C" cement from 905'-708' calc TOC. 4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
4/6/17 – Tagged TOC at 737'. ND BOP. Spotted 15 sx Class "C" cement from 129' to surface inside 5-1/2" casing. Topped out casing. 4/11/17 – Dug out cellar and cut off wellhead. Installed dry hole marker 3' below ground level. NOTE: Sent GPS coordinates and picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
picture to Artesia NMOCD. WELL IS PLUGGED AND ABANDONED.
wing of well box aned Plugdes
proved for Multiple is return of Web Page under
Spud Date:  Rig Release Date:  R
Spud Date:  Rig Release Date:  Right Plusting Part All Plusting Par
I hereby certify that the information above is true and complete to the best of my knowledge and belief
SIGNATURE DATE April 13, 2017
Type or print name Tina Huerta E-mail address: tina huerta@eogresources.com PHONE: 575-748-4168  For State Use Only
APPROVED BY: Mart & Byel TITLE COMPLIANCE OFFICED DATE 4/19/2017