## NM OIL CONSERVATION ARTESIA DISTRICT

Form 3160-5 (June 2015)

**UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT AUG 2 1 2017

FORM APPROVED

OMB	NO. 1004-0137 January 31, 201
Lease Serial No.	

SUNDRY NOTICES AND REPORTS ON WELLS.

	in forms for any position of		スピクドリカド	3	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or	Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agree NMNM71016G	7. If Unit or CA/Agreement, Name and/or No. NMNM71016G	
1. Type of Well			8. Well Name and No. POKE LAKE UNIT	203	
☑ Oil Well ☐ Gas Well ☐ Other					
2. Name of Operator Contact: TRACIE J CHERRY BOPCO LP E-Mail: tracie_cherry@xtoenergy.com			9. API Well No. 30-015-32883		
3a. Address 6401 HOLIDAY HILL RD BLDG 5 SUITE 200 MIDLAND, TX 79707  3b. Phone No. (i			ea code)	10. Field and Pool or Exploratory Area NASH DRAW;DEL/BS (AV SND)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, S	11. County or Parish, State	
Sec 7 T24S R30E Mer NMP SWSE 660FSL 1980FEL			EDDY COUNTY	EDDY COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NOTIC	E, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
☑ Notice of Intent	☐ Acidize	☐ Deepen	☐ Prod	uction (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Hydraulic Frac	turing 🔲 Recla	nmation	■ Well Integrity
☐ Subsequent Report	Casing Repair	☐ New Construct	ion 🔲 Reco	mplete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Aban		oorarily Abandon	
	Convert to Injection	☐ Plug Back	☐ Wate	r Disposal	
following completion of the involved testing has been completed. Final At determined that the site is ready for fi BOPCO, LP respectfully subm well.	pandonment Notices must be filed of inal inspection.	nly after all requirement	s, including reclama	tion, have been completed a	1-4 must be filed once and the operator has
Procedure is as follows:					
<ol> <li>MIRU plugging company. F POOH w/tbg.</li> </ol>	POOH w/rods and pump. ND	WH and NU 3K ma	nual BOP. Fund	tion test BOP.	
2. RU WL. RIH w/5-1/2" CIBP top of CIBP. (Perf plug)	to 6,010', set. RBIH tag to v	erify setting. Pump 2	25 sxs Class C o	emt on	
3. PUH to +/-5,825', 9.5# salt	gel from +/-5,825' to 2,500'.				
14. I hereby certify that the foregoing is	Electronic Submission #384	955 verified by the B		ion System	d for fecord
Name (Printed/Typed) TRACIE J CHERRY Title		REGULATORY A	ANALYST	4101,	
				20/18	1004
Signature (Electronic S	Submission)	Date 0	8/16/2017	CCSA 1	THE LAND
	THIS SPACE FOR	FEDERAL OR ST	ATE OFFICE	USE	N.
Approved By		Title			1
Approved By		<del> </del>		BLM approvals will	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Pending Subseque	ently be reviewed	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			igly and scan	ned	ed

## Additional data for EC transaction #384955 that would not fit on the form

## 32. Additional remarks, continued

- 4. PUH to 3,655', spot 50 sxs CI C cmt from 3,655' to 3,210'. (Fluid used to mix the cement for the Salt section of this plug shall be saturated with the salts common to the section and in suitable proportions). WOC & Tag. (T/Del, B/Salt Plugs)
- 5. RIH with jet cutter for 5-1/2" 15.5# casing. Cut casing at 2,500'. Circulate 9.5# salt gel to from 2,500' to surface. Pull 5-1/2" casing.
- 6. RIH with tubing to 2,550", spot 45 sxs Class C cmt from 2,550' to 2,450'. WOC and tag (Csg Stub plug).
- 7. PUH to 990', spot 90 sxs Class C cmt from 990' to 745'. WOC and tag (T/Sait, 8-5/8" shoe plug).
- 8. PUH to 60', spot 21 sxs Class C cmt from 60' to surface. Verify to surface (Surface plug).
- 10. ND BOP and cut off wellhead 5' below surface. Set P&A marker.