Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD-ARTESIA

FORM APPROVED OMB No. 1004-0135

Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				5. Lease Serial No. LC-049945-B			
				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well Oil Well Gas Well Other				8. Well Name and No.			
2. Name of Operator				Parrot Federal Com #2			
Yates Drilling Company				9. API Well No.			
	3b. Phone No. (inclu	•	i	30-015-33345			
105 S. 4th Str., Artesia, NM 88210 505-748-8463 4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)				10. Field and Pool, or Exploratory Area Wildcat Chester			
,			11. County or Pa				
1600' FSL and 660' FEL Section 29-19S-27E				Eddy, NM			
12. CHECK APPROPRIATE BOX(ES) TO IN	DICATE NATU	JRE OF NC	TICE, REP	ORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
X Notice of Intent Subsequent Report Change Plans Convert to Injection 13. Describe Proposed of Completed Operation (clearly state all pertinent details, includir If the proposal is to deepen directionally or recomplete horizontally, give subsurface to Attach the Bond under which the work will be performed or provide the Bond No. or following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notices shall be filed only after all determined that the site is ready for final inspection.)	ocations and measured and if it with BLM/BIA. Recompletion or recomplial requirements, including	e of any proposed and true vertical de equired subsequer etion in a new inte	Reclamation Recomplete Temporarily Water Dispos work and approxir epths of all pertinent reports shall be rival, a Form 3160-	mate duration thereof. Int markers and zones. It is a days.	Water Shut-Off Well Integrity Other		
 Blow well down to steel pit and ND Tree and NU 5,000# BOP POH with tubing and TCP gun and packer 							
Pickup redressed packer and RIH with packer and tbg							
Set and test packer and casing							
5. Acidize well with 5,000 gals 15% gelled NEFE acid with 250) ball sealers						
6. Flow well back and clean well up							
7. POH with tbg and packer and RIH with mud joint, perforated8. Return well to production	a sub, seating nipi	ole and tog. Fi	ange weii up a	and RIH With pur	ip and rods		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Karen J. Leishman	Title	Operatio	ns Tech				
V ~ (0 1				······································			
Signature of aven of Llechman.	Date	March 30	0,2006				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by Conditions of approval, if any, are attached. Approval of this notice does no		TRIMETA	<u>y engin</u>	Date	APR 1 1	2006	

Office

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.