Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018
Loose Cariel No.

	Expires: January 31, 2018
5.	Lease Serial No. NMLC028936C

SUNDRY)CD 5. Lease S	5. Lease Serial No. NMLC028936C					
Do not use thi abandoned wel		6. If Indian, Allottee or Tribe Name					
SUBMIT IN	7. If Unit	7. If Unit or CA/Agreement, Name and/or No.					
Type of Well		ame and No. RAL S 7					
2. Name of Operator ROVER OPERATING, LLC	Contact:	CONNIE SWAN wanderlandok.com	9. API Well No. 30-015-31953				
3a. Address 17304 PRESTON ROAD, SUI DALLAS, TX 75252	TE 740	3b. Phone No. (include area code) Ph: 918-621-6533		10. Field and Pool or Exploratory Area LOCO HILLS; GLORIETA-YESO			
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description)	11. Coun	ty or Parish, State			
Sec 28 T17S R30E Mer NMP 32.811931 N Lat, 103.979682				Y COUNTY, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/I	Resume)			
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	☐ New Construction	□ Recomplete	☐ Other			
☐ Final Abandonment Notice	□ Change Plans	Plug and Abandon		don			
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.							
Starting date: Upon approval				Accepted for record			
MIRU POH rods, tubing TIH and set pkr 75? above top perforation, test casing to 500 psi for 30 min SEE ATTACHED FOR POH, RU WL, run CBL Conformation TIH with CIBP, set 75? above top perforation Contact BLM and conduct MIT test.							
SI well, RDMO Bond coverage: BLM Bond Fil	e No. NMB001378			ARTESIA DISTRICT			
Sout in w/out approval sma 8/2016 / MAR 12 2018							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #405118 verified by the BLM Well Information System							
For ROVER OPERATING, LLC, sent to the Carlsbad							
Committed to AFMSS for processing by JENNIFER SANCHEZ on 02/28/2018 () Name (Printed/Typed) CONNIE SWAN Title REGULATOR//ADMINISTRATORY							
THE RESIDENCE OF THE PROPERTY							
Signature (Electronic S	118						
THIS SPACE FOR FEDERAL OR STATE OF ICE MISE 2018							
Approved By Conditions of approval, if any, are attache			BIRFAU OF LAND CAR! SBAD FIEL	Dad Dad			
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 1 year ending 03/06/2019 subject to conditions of approval. Temporary Abandonment of Wells on Federal Lands

lemporary Abandonment of Wells on Federal Lan Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with wellbore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Federal S 7

- 1. Well is approved to be TA/SI for a period of 1 year or until 03/06/2019
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 03/06/2019
- 3. COA's met at this time.