Submit 1 Copy To Appropriate District Office State of New Mexico Office State of New Mexico	Form C-103 Revised July 18, 2013
District I – (575) 393-6161 Energy, Minerals and Natural Resources District II – (575) 748-1283	WELL API NO.
1625 N. French Dr., Hobbs, NM 88200 District III – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 District III – (505) 334-6178 1220 South St. Francis Dr.	30-015-03569
811 S. First St., Artesia, NM 88210 QL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 88218 District IV – (505) 476-3460	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 CHAIDSON OTICES AND REPORTS ON WELLS	7. Lease Name of Unit Assessment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Continental State
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	009
2. Name of Operator	9. OGRID Number
EOG M Resources Inc.	15445
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth St, Artesia, NM 88210	Turkey Track 7 Rvrs Qn GB SA
4. Well Location	
Unit Letter P : 330 feet from the South line and 330 feet from the East line	
Section 9 Township 19S Range 29E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Elevation (Show whether DK, KRB, K1, OK, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐	
	RILLING OPNS. PANDA
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
4/05/18—MIRU.	
4/06/18—POOH w/ rods ok'd to spot 25 sxs @ 2134' (inside production tbg) CTOC 2 1980' SIW.	
4/09/18—Tag @ 2140' cut tbg @ 2095' circ well w/ brine worked on WH.	
4/10/18—POOH prod. tbg RIH w/ GR to 1970', set 7" CIBP @ 1968' circ well w/ MLF cap BP w/ 25 sxs CTOC @ 1784'.	
4/11/18—Tag @ 1808' perf @ 1600' set pkr @ 1301' press up OCD ok'd to spot 25 sxs @ 1649' CTOC @ 1495' (OCD ok'd no perf @ 1283'). Spot 55 sxs @ 1301' CTOC 2 963' WOC Tag @ 1007', perf @ 345' sqz 85 sxs CTOC @	
200'.	
4/12/18—Tag @ 238' OCD ok'd to perf @ 200' sqz 30 sxs CTOC @ 100' SIV	N.
4/13/18—Tag @ 162' spot 55 sxs from 162' to surface verified RDMO.	•
	-
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
$A_1 \cdot Q_2$	
SIGNATURE TITLE Agent_	DATE4/23/18
V/cu_moddoc	@ ecgresources com 432-686-3658
	PHONE: 472 (10 70)
For State Use Only	
LEDDOUGH DU STATE STATE	DATE 4-25-18
APPROVED BY: Aft of TITLE SAFE MAY	DATE 1-25 10
Conditions of Approval (if any):	