Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC028784A

SUNDRY NOTICES AND REPORTS ON THE 138 2018  Do not use this form for proposals to drill or to re-enter an	NMLC
Do not use this form for proposals to drill or to te-emer an	6 If Indian

. Allottee or Tribe Name

abandoned wel	II. Use form 3160-3 (APD) for s	Such proposals.	.D.	,		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM88525X		
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. BURCH KEELY UNIT 405		
Name of Operator Contact: KANICIA CASTILLO COG OPERATING LLC E-Mail: kcastillo@concho.com				9. API Well No. 30-015-35439-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701  3b. Phone No. (include area code) Ph: 432-685-4332				10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPPER YE		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State			
Sec 24 T17S R29E SWNE 1885FNL 2470FEL				EDDY COUNT	Y, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	DICATE NATURE O	F NOTICE,	REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION		TYPE OF	E OF ACTION			
Notice of Intent	☐ Acidize	□ Deepen	☐ Producti	ion (Start/Resume)	■ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama	ation	■ Well Integrity	
Subsequent Report	☐ Casing Repair	■ New Construction	Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Tempora	arily Abandon		
	☐ Convert to Injection	☐ Plug Back	☐ Water D	Disposal		
testing has been completed. Final Aldetermined that the site is ready for for 104/10/18 MIRUP plugging equivalent rods & 6 K-Bars. Could not bg & TAC. Set 5 1/2" CIBP @ Spotted 25 sx cmt @ 4084-38 2980'. Spotted 25 sx class C 04/12/18 Tagged plug @ 808 cmt @ 462" & circulated to su welder. Dug out cellar. Cut of	uipment. Dug out cellar. ND wel of unset pump. POH w/ 2 7/8" ro 4084'. Circulated hole w/ MLF. 331'. Spotted 30 sx cmt w/ 2% Ccmt w/ 2% CACL @ 2637-2384'. ND BOP. Perfd csg @ 60'. Prefface. Rigged down and moved f well head. Verified cmt to surfar. Cut off deadmen. Cleaned loc	I head, NU BOP. Unse ods. 04/11/18 Continue Pressure tested csg, hACL @ 3248-2945'. W. Spotted 25 sx cmt @ essured up on perfs. Spotted 12 sy continue of 10/10/18 Moved in ce. Welded on "Under	at TAC. POH at POH w/ 2 held 500 psi. OC. Tagged 1061-808'. V potted 50 sx backhoe and ground Dry	w/ 170 7/8"  plug @ VOC. Class C RECI	AMATION  10.12.18  MATION PROCEDURE ATTACHED	
	Electronic Submission #412320	TING LLC. sent to the C	arisbad 04/20/2018 (1			
Signature (Electronic	Submission)	Date 04/19/2	2018			
	THIS SPACE FOR FE	DERAL OR STATE	OFFICE D	DEFOR RECO	IRD	
_Approved By		Title		4 4 0010	Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to conditions.	uitable title to those rights in the subject uct operations thereon.	t lease Office	MAY	1 1 2018		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime f statements or representations as to any	or any person knowingly and matter within its jurisaiction	a Blilthingtoffi CARLSB	akê kolanîy Alepa <del>liko Mil</del> AD FIELD OFFICE	agency of the United	
(Instructions on page 2) ** BLM REV	/ISED ** BLM REVISED ** B	LM REVISED ** BL	M REVISE	** BLM REVIS	ED **	



## United States Department of the Interior

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico ·88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612