Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 Energy, N	Ainerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	OCD Artesia	WELL API NO.
011 0.1 1131 01., 7 1110314, 7 1111 00210	NSERVATION DIVISION	30-015-05586
1000 Bio Brazas Pd Astes NM 97410	O South St. Francis Dr.	5. Indicate Type of Lease FEDERAL
	Šanta Fe, NM 87505	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No. NM-014102
SUNDRY NOTICES AND REP	ORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		North Shugart Queen Unit
1. Type of Well: Oil Well X Gas Well Oth	er	8. Well Number 008
2. Name of Operator		9. OGRID Number
State of New Mexico formerly Tom R. Come	/	188152
3. Address of Operator		10. Pool name or Wildcat
1725 N. French Drive Hobbs, NM 88240		Shugart; Yates-7RV-Q-GB
4. Well Location		
Unit LetterI:2310 feet	from theSouth line and	_330feet from theEastline
	vnship 18S Range 31E	NMPM Eddy County
	(Show whether DR, RKB, RT, GR, et	
The valida	(Show whether DR, RRD, RT, OR, et	
Manager and the production of the second sec		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INT SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON INT TO PA COMMENCE DRILLING		
PULL OR ALTER CASING P&A NR CASING/CEMENT JOB		
DOWNHOLE COMMINGLE P&AR PVV		
Park		
OTHER:	_ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
proposed completion of recompletion.		ACCEPTED FOR RECORD
		ACCEPTED FOR RECORD
18		
GC 5-24-18 Accepted for record NMOCD	SEE ATTACHED	MAY 1 7 2018
Gated for record . Itim	SEE III INCILED	MAT 1 2010
Accepted		4/6
		RULE AU OF LAND MANAGEMENT
		CARLSBAD FIELD OFFICE
I hereby certify that the information above is true an	d complete to the best of my knowled	lge and belief.
I hereby certify that the information above is true an	d complete to the best of my knowled	lge and belief.
SIGNATURE		
SIGNATURE	TITLE	DATE
SIGNATURE Type or print name	TITLE	
SIGNATURE	TITLE E-mail address:	DATE
SIGNATURE Type or print name	TITLE	DATE

RECEIVED

MAY 2 3 2018

DISTRICT II-ARTESIA O.C.D.

Plugging Report North Shugart Queen Unit #8 API: 30-015-05586

4/11/2018 Cleared location and moved in. Rigged up. No rods. Installed the BOP. Tubing was stuck. Loaded casing with 2 bbls of fresh water and tubing with less than I bbl. Stretch test showed tubing to be stuck at 1060'. RIH with wireline and sat down inside tubing at 11'. Attempted to screw onto the fish with 3/4" and 5/8" rods boxes and pins. No success. Worked tubing and got to go down 2" and up 5". Pulled 60 points over and fluid started to run over the BOP. The flow was very small and then some gas bubbles appeared. Worked tubing again and flow stopped. Left 60 points pulled on tubing. Clased in the well and SION.

4/12/2018 Worked tubing free, but could only gain down hole. Worked down hole 1 full joint and got stuck again. Performed 2 more stretch tests and showed tubing stuck @ 1115' and 1157'. RIH with outside back off tools and sat down at 1134'. Back off collar closest to 1000'. Got the back off in one shot. Laid down 2 joints and RIH with rods and tagged fish at 40'. Fish is not coming out of the hole with the tubing. Assume there is a full rod string in the hole. RIH with the 2 joints that were laid down and spotted 35 sx cement on top of back off. POOH 10 stands and SION.

4/16/2018 Caught fish at 40' with overshot. Backed off 8 rods. Made second attempt and caught 2 additional rods. Fish now at 290'. POOH with 16 joints of tubing. 31 total joints were recovered from the outside back off from 976'. ETOC at 639'. Set packer at 252' and tested plug below the packer to 800#. Held good. Isolated holes in 5 ½' casing between 63' and 126'. Perforated casing at 285' and set packer at 126'. Established rate and pumped cement down the tubing, under the packer to the perfs at 285' and to surface behind the 5½' casing. Took 75 sx to get cement to surface. Rigged down. Brought in another load of fresh water to water the road. SION.

4/17/2018 Moved rig and equipment off location with the assistance of a 4WD loader. Dug out and cut off. Filled up 5 ½"X 8 5/8" annulus to surface from 35' with 5 sx cement. 5 1/2" casing took less than a sack to fill up. Installed marker and cut off anchors. Cleaned the pit.

は一つしつは一つのほのの CHILD CEEVUNE O OF WIN FOR TOW R COME

