Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

NM OIL CONSERVATION **OCD** Artesia

١.	FORM APPROVED
	OMB NO. 1004-0137
	Expires: January 31, 2013

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

ARTESIA DISTRIC JUN 27 2018 Lease Serial No. NMNM04557

abandoned we	II. Use form 3160-3 (APL)) for such propo		RECEIVE	o. Il liidiali, Allottee C	i Tibe Name			
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.								
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Oil	8. Well Name and No. BIG EDDY 122								
Name of Operator BOPCO LP		9. API Well No. 30-015-27454-00-S1							
3a. Address 6401 HOLIDAY HILL RD BLD MIDLAND, TX 79707	3b. Phone No. (incl Ph: 432-620-43	ude area code) 36		10. Field and Pool or Exploratory Area S HACKBERRY					
4. Location of Well (Footage, Sec., 7		11. County or Parish, State							
Sec 4 T20S R31E SENW 198		EDDY COUNTY, NM							
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE N	IATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA			
TYPE OF SUBMISSION	ACTION								
☐ Notice of Intent	☐ Acidize	Deepen		☐ Producti	on (Start/Resume)	■ Water Shut-	Off		
_	☐ Alter Casing	Hydraulic	Fracturing	☐ Reclama	ation	■ Well Integri	ity		
Subsequent Report	Casing Repair	■ New Con	struction	☐ Recomp	lete	□ Other			
☐ Final Abandonment Notice	□ Change Plans	🔁 Plug and	Abandon	☐ Tempora	arily Abandon				
	☐ Convert to Injection	☐ Plug Bac	k	□ Water D	r Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BOPCO, LP respectfully submits this sundry notice to report plug and abandonment of the referenced well. O5/17/2018 to 5/21/2018 POH with tubing. PT casing to 500 psig. PUH spot 25 sxs balanced plug form 4300-4100. WOC. Tag cmt top 4078, Set packer at 2339. Perf sgz holes at 2950, would not circulate. BLM suggested 55sxs spot. RIH and spotted 55 sxs balance plug from 3003-2459. WOC O5/22/2018 to 5/23/2018 RIH and tag cmt top at 2497. Move packer up to 800. Perf sqz holes at 1100. Pump 150 sxs from 1100-800. WOC. Release packer. Tag cmt at771. 14. I hereby certify that the foregoing is true and correct.									
t nortely comp and are loregoing to	Electronic Submission #4	23858 verified by t	he BLM Well	l Information	System				
For BOPCO LP, sent to the Carlsbad Committed to AFMSS for processing by DEBCRAH MCKINNEY on 06/14/2018 (09KMS0825S)									
Name (Printed/Typed) TESSA FI	TZHUGH	Title	REG. AN	NALYST					
Signature (Electronic S	ubmission)	Date	06/13/20	018	COEDIED EO	D 05000	 a_		
	THIS SPACE FO	R FEDERAL O	R STATE (OFFICE US	FOLL IED LO	K KEUUKI	7		
Approved By		Titl	e		JUN 18	2018 Date			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu		ce		RUDY ALL OF LAND	MANAGEMENT				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a catalements or representations as t	rime for any person k o any matter within it	nowingly and s s jurisdiction.	willfally to mai			d		
Instructions on page 2) ** BLM REVI	SED ** BLM REVISED	** BLM REVIS	ED ** BLM	REVISED	** BLM REVISED) ** ′			

Additional data for EC transaction #423858 that would not fit on the form

32. Additional remarks, continued

05/24/2018 to 5/29/2018
Start pumping surface plug, well went on vacuum. BLM decided to pump 25 sxs then displace 1.5 bbls to perfs at 60. WOC. Well on vaccum. Decided to pump 100 sxs. C cmt, then displace 1.5 bbls to perfs at 60. WOC.

05/30/2018 to 06/08/2018
Broke circulation. Pumped 53 sxs to surface on 13 5/8 & 8 5/8 casing valves, closed valves.
Squeezed an additional 15 sxs down 5 1/2 casing. SI well. Pumped total of 70 sxs for surface plug.
All operations witnessed by Terry Wilson with the BLM. Verified cmt top (Wilson ok?d). Installed DHM (pics sent to BLM, ok?d). Well plugged and abandoned.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612