Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resou	rces Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	ON 30-015-01946
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE \(\overline{X} \) FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROP	CICES AND REPORTS ON WELLS DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Artesia Metex Unit
1. Type of Well: Oil Well	Gas Well Other	8. Well Number 25
2. Name of Operator State of New Mexico for	merly Canyon E&P Company	9. OGRID Number 269864
3. Address of Operator		10. Pool name or Wildcat
	Hobbs, NM 88240	Artesia QU-GB-SA
4. Well Location Unit Letter O: 660 feet from the South line and 1650 feet from the East line		
Unit Letter U : 660 feet from the South line and 1630 feet from the East line Section 19 Township 18S Range 28E NMPM County Eddy		
Section 19	11. Elevation (Show whether DR, RKB, RT,	
de Bullion Alla		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		AL WORK ALTERING CASING
TEMPORARILY ABANDON		NCE DRILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE		CEMENT JOB
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
		HOBBEC
		HOBBS C.C.
	SEE ATTACHMEN	TS JUL 1 0 2018
		RECEIVED
Spud Date:	Rig Release Date:	
I hereby certify that the information	a above is true and complete to the best of my k	nowledge and helief
SIGNATURE Wash	TITLE Petroleum En	gr Specialist DATE 07/10/2018
Type or print name Mark White		PHONE: 575-393-6161
For State Use Only	L-iliali audicss.	1 1 1 1 1 1
APPROVED BY: WALL STOWN TITLE HO/I DATE 7/11/2018		
Conditions of Approval (if and):		


Canyon E&P Company Artesia Metex Unit No. 25 30-015-01946 660' FSL & 1650' FEL UL – O, Sec. 19, T18S, R28E

8 5/8" csg at 455' w/ 30 sx cmt. 6 5/8" csg at 1937' w/ 100 sx cmt. OH 1937' – 2460' TD 2460'

- 1. MIRU plugging equipment. POOH w/ production equipment.
- 2. Run gauge ring. Set CIBP at 1850'. Circulate hole w/ mud laden fluid and pressure test casing to 500 psi.
- 3. Spot 65 sx cement.
- 4. Perforate at 505'. Pump sufficient cement to circulate to surface inside/outside of 6 5/8" casing.
- 5. Cut off wellhead 3 feet below ground level.
- 6. Verify cement to surface on all strings.
- 7. Install upright P&A marker and cut off anchors.

NOTES: Mud laden fluid consists of 9.5 ppg with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

Canyon E P Company Artesia Metex Unit No. 25



8 5/8" @ 455' w/ 30 sx

NOTES:

200 Qts Nitro 2089' - 2160'

12 1/2" hole to 220', 9 3/4" hole to 455'

8 1/4" hole to TD

6 5/8" @ 1937' w/ 100 sx OH 1937' - 2460' TD 2460'

Canyon E P Company Artesia Metex Unit No. 25

PROPOSED

30-015-01946



INSTALL P&A MARKER VERIFY CMT TO SURFACE CUT OFF WELLHEAD 3' BELOW GL

8 5/8" @ 455' w/ 30 sx

CIRCULATE CEMENT TO SURFACE. PERF AT 505'.



SPOT 65 SX CMT* CIRC MLF. PRESSURE TEST CSG. **SET CIBP AT 1850'.**

6 5/8" @ 1937' w/ 100 sx OH 1937' - 2460' TD 2460'

* NO TAG NECESSARY IF CSG TESTS GOOD