Form 3160-5 (Sune 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No.		
					NMLC069627A 6. If Indian, Allottee or Tribe Name		
							SUBMIT IN TRIPLICATE - Other instructions on page 2
Type of Well					8. Well Name and No. HUDSON FEDERAL 001		
2. Name of Operator Contact: TRACIE J CHERRY				-	9. API Well No.		
BOPCO LP E-Mail: tracie_cherry@xtoenergy.					30-015-21052		
3a. Address 6401 HOLIDAY HILL RD BLDG 5 MIDLAND, TX 79707		3b. Phone No. (include area code) Ph: 432-221-7379			10. Field and Pool or Exploratory Area DELAWARE; SWD		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description NM OIL C Sec 1 T23S R30E Mer NMP SENW 1830FNL 1980FWL ARTES			ONSERVATION 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		11. County or Parish, State EDDY COUNTY, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O		REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	ISSION RECEIVED PE OF ACTION						
□ Notice of Intent	☐ Acidize	☐ Deep	☐ Deepen		ion (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing ☐ Reclamatio		ation	■ Well Integrity		
Subsequent Report	☐ Casing Repair ☐ Nev		Construction	☐ Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans ☑ Plu		and Abandon		arily Abandon		
	☐ Convert to Injection ☐ Plu		Back Water l		Disposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi BOPCO, LP respectfully subm	k will be performed or provide operations. If the operation re- brandonment Notices must be fil- inal inspection.	the Bond No. on sults in a multiple ed only after all r	file with BLM/BIA completion or reco equirements, includ	Required submpletion in a ling reclamation	bsequent reports must be new interval, a Form 3160 n, have been completed a	filed within 30 days 0-4 must be filed once	
MIRU. ND wellhead, install BOP. Function test. POOH with tbg and pkr. Circulate hole with 10# brine. RIH and tag cement retainer @ 5038'. Drill on retainer. Unable to drill out.							
03/22/18 - 03/23/18 Notified BLM. Okay to stop drilling and continue plugging. RIH w/7-5/8" CIBP, set @ 3940'. Tag to verify setting. Pump 70 sxs Class ?C? 3940' - 3582'.							
03/26/18 - 03/28/18 Tag TOC @ 3600'. RIH cut 7-5/8" csg @ 3550'. Attempt to pull csg w/no movement. Notify BLM. Set pkr							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #429120 verified by the BLM Well Information System For BOPCO LP, sent to the Carlsbad							
Name (Printed/Typed) TRACIE J CHERRY			Title REGUL	Title REGULATORY COORDINATOR			
Signature (Electronic Submission) Da				018			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By			Title			Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe s to any matter w	rson knowingly and thin its jurisdiction	l willfully to m	ake to any department or	agency of the United	

Additional data for EC transaction #429120 that would not fit on the form

32. Additional remarks, continued

@ 30', load hole and PT 7-5/8" to 500 psi (good). Run CBL on 7-5/8" csg. Cut csg @ 3510'. POOH w/7-5/8" csg.

03/29/18

Run CBL from 3500'. Good cmt. Notify BLM. Spot 150 sx Class ?C? 3600' - 3100'. SDFWE

04/03/18 - 04/05
Tag TOC @ 3100'. Ok?d by BLM. Pump 500 sxs cmt. Tag TOC @ 1861', Pump 612 sxs Class ?C?. Tag TOC @ 471'. BLM witness tag. Pump 25 sxs Class ?C?. Tag @ 391'. Perf @ 60', PT 10-3/4" csg (good). TIH to 110', pump 45 sxs Class ?C? to surface.

Cut off wellhead. Install marker. Well P&A?d