UNITED STATES DEPARTMENT OF THE INTER OR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED

	-	 Carlot Ma			_	
į		Expires:	: Janı	uary 3	11.	20
		OMB				

'AUG 1 7 2018 Expires:
OCD Artesia 5. Lease Serial No.
NMNM94839 SUNDRY NOTICES AND REPORTS ON WELLS

South	NOTICES AND REFOR	"" OIT TIL	LLO CO		1					
Do not use thi abandoned wei	6. If Indian, Allottee or Tribe Name									
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No.									
Type of Well Oil Well	8. Well Name and No. WIGEON 23 FED COM 1									
Name of Operator CIMAREX ENERGY COMPAN	9. API Well No. 30-015-33563-00-S1									
3a. Address 202 S CHEYENNE AVE SUIT TULSA, OK 74103.4346	E 1000	(include area code) 7-3033		10. Field and Pool or Exploratory Area WHITE CITY-WOLFCAMP Purple Sage Wolfcamp						
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)			11. County or Parish,	tate					
Sec 23 T25S R26E NWSE 16	50FSL 1650FEL			EDDY COUNTY, NM						
12. CHECK THE AF	PPROPRIATE BOX(ES) T	O INDICA	ΓE NATURE O	F NOTICE,	, REPORT, OR OTH	ER DATA				
TYPE OF SUBMISSION		TYPE OF	ACTION							
☐ Notice of Intent	☐ Acidize	□ Deep	oen	☐ Product	tion (Start/Resume)	■ Water Shut-C)ff			
	☐ Alter Casing	☐ Hyd	raulic Fracturing	□ Reclam	nation	■ Well Integrity				
Subsequent Report	□ Casing Repair	Casing Repair		plete	Other					
☐ Final Abandonment Notice	□ Change Plans	🛛 Plug	and Abandon	□ Tempo:	rarily Abandon					
	☐ Convert to Injection	Plug	☐ Plug Back ☐ Wat		er Disposal					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 08/04/18: SET 4-1/2"CIBP @ 9.150'; CIRC. WELL W/ MLF.; PUMP 70 SXS.CMT. @ 9.150'. 08/05/18: CUT 4-1/2" CSG. @ 8.000' - NOT FREE; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,500# X HOLD; PUMP 25 SXS.CMT. @ 8.050'(PER BLM); WOC. 08/06/18: TAG CMT. @ 7.828'(OK'D BY BLM); CUT 4-1/2" CSG. @ 6,227' - NOT FREE; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 2,000#; PUMP 30 SXS.CMT. @ 6,277'; WOC. 08/07/18: TAG CMT. @ 5,794'(OK'D BY BLM); ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,500# X HOLD; PUMP 30 SXS.CMT. @ 5,580'(PER BLM); WOC. 08/08/18: TAG CMT. @ 5,140'(OK'D BY BLM); CUT X PULL 4-1/2" CSG. @ 2000'. 08/09/18: PERF. SQZ. HOLES IN 7" CSG. @ 2,000'; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,600# X HOLD; PUMP 50 SXS.CMT. @ 2,050'(PER BLM); WOC. 08/10/18: TAG CMT. @ 1,767'(OK'D BY BLM); PERF. SQZ. HOLES IN 7" CSG. @ 1,739'; ATTEMPT TO EST. ECLAMATION INJ. RATE - PRES. UP TO 1,600# X HOLD; PUMP 50 SXS.CMT. @ 1,507' DUE. 2-12-19'										
14. I hereby certify that the foregoing is Comm Name (Printed/Typed) DAVID A	Electronic Submission #43 For CIMAREX ENER itted to AFMSS for procession	30949 verifie IGY COMPA ng by DEBO	d by the BLM Welly OF CO, sent to RAH MCKINNEY Control Title AGENT	o the Carlsb on 08/14/201	n System oad 8 (18DLM0545SE)					
Signature (Electronic S	Submission)		Date 08/13/2	018	ACCEPTED F	OR RECOR	D			
	THIS SPACE FOI	R FEDERA	L OR STATE	OFFICE U	SE	4 2010				
				AUG	4 2018					
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equ	uitable title to those rights in the s	Title			D MANAGEMENT TELD OFFICE	1				
which would entitle the applicant to condu	oct operations thereon.		Office	210.11						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #430949 that would not fit on the form

32. Additional remarks, continued

PERF. SQZ. HOLES IN 7" CSG. @ 1,180'; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,600# X HOLD; PUMP 30 SXS.CMT. @ 1,230'(PER BLM); WOC X TAG CMT. @ 1,049'(OK'D BY BLM); PERF. SQZ. HOLES IN 7" CSG. @ 453'; ATTEMPT TO EST.INJ.RATE - PRES.UP TO 1,200# X HOLD; PUMP 40 SXS.CMT. @ 503'(PER BLM); WOC. 08/12/18: TAG CMT. @ 294'(OK'D BY BLM); PERF. X CIRC. TO SURE, FILLING ALL ANNULI, 50 SXS.CMT. @ 100'-3'; DIG OUT X CUT OFF WELLHEAD 3'B.G.L.; VERIFY CMT. TO SURF. ON ALL ANNULI; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.

WELL PLUGGED AND ABANONDED 08/12/18~



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612