Form 3160-5 (August 1999)

Oil Cons. N.M. DIV-Dist. 2 UNITED STATES 1301 W. Grand Avenue DEPARTMENT OF THE INTERIOR Artesia NM 88215

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Artesia, NM 882105. Lease Serial No. **BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 324 25 26 abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side 2003 7. If Unit or CA/Agreement, Name and/or No. Type of Well RECEIVED Oil Well Gas Well Other OCD - ARTESIA Well Name and No. Name of Operator 3a. Address 3b. Phone No. (include area 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Jec 14, T255, R26E 11. County or Parish, State L+5CO FEL 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize Deepen Production (Start/Resume) ■ Water Shut-Off ■ Notice of Intent Well Integrity ■ Alter Casing ☐ Fracture Treat Reclamation Casing Repair ■ New Construction Recomplete Other ☐ Subsequent Report Plug and Abandon ☐ Change Plans Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) ALL WORK Completed - 5-7-03

Except SurFace cleanup See Attached

Accorded as to plugging of the well borns.
Libbility under bond is retained until
surface restoration is competed.

OPERATORS - FOR SUNDRIES SUBMIT 1 ORIGINAL AND 5 COPIES

Surface restoration is competed.			ACCEPTED FOR RECORD		
والمراوع والماران وا	. apprime yet				
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title	Quener	JUN 2 () 2003	
Signature Patry Rich	Date	6-7-03	LES BABYAK PETROLEUM ENGINEER		
THIS SPACE FOR	FEDERAL OR	STATE OFFICE USE			
Approved by	Title		Date		
Conditions of approval, if any, are attached. Approval of this notice do certify that the applicant holds legal or equitable title to those rights in which would entitle the applicant to conduct operations thereon.		Office			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

BILLY & PATSY RICH

Lease: H.M. FEDERAL # 1

Project: P & A – CEMENTING REPORT

04-24-2003 - SET CIBP @ 1909' - SPOT 25 SXS CEMENT ON TOP - 1600'

04-25-2003 - PULL 1250' OF CASING

04-25-2003 - SPOT 35 SXS @ 1306'-1185' TAG

04-25-2003 - SPOT 70 SXS @ 217'-31' & TAG

04-28-2003 - SPOT 15 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10#'MUD

MAYO MARRS CASING PULLING INC.

BILL & PATSY RICH

Lease: H.M. FEDERAL # 1

Project: P & A

JOB # 03-

4-24-03

NOTIFY BLM - KNOCK DOWN HILL ON LOCATION WITH BACKHOE - MOVE PUMP JACK IN ORDER TO RIG UP - MIRU - NUBOP -- POOH WITH RODS & FUBING - RIH & SET CIBP @ 1909' WITH MMCPI WORKSTRING & SPOT 25 SXS @ 1909'1600' - PER HOMER SAENZ BLM - POOH WITH TUBING - CLOSE IN WELL

4-25-03

CUT CASING @ 1250' - LAY DOWN 4 1/2" CASING - RIH & SPOT 35 SXS @ 1306' POOH - WOC - RIH & TG @ 1185' - POOH & SPOT 35 SXS @ 217' - POOH - CLOSE IN WELL

4-28-03

RIH & NO TAG – RESET PLUG – SPOT 35 SXS @ 217' – POOH – WOC -RIH & TAG @ 31' – INSTALL DRY HOLE MARKER WITHS SXS CEMENT @ 30' TO SURFACE – RIG DOWN CUT OFF WELLHEAD & ANCHORS – LEVEL PIT & CELLAR - MOVE OUT (2 HRS RIG TO RESET PLUG)

MMCPI WORKSTRING 2 HRS RIG BID 60 SXS USED 135 BID \$ 7,470.00