

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia Field OfficeFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM2748

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
GISSLER B 149. API Well No.
30-015-22004-00-S110. Field and Pool or Exploratory Area
SQUARE LAKE11. County or Parish, State
EDDY COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BURNETT OIL COMPANY INC

Contact: TINA HUERTA

E-Mail: tina_huerta@eogresources.com

3a. Address

801 CHERRY STREET UNIT 9
FORT WORTH, TX 76102-6881

3b. Phone No. (include area code)

Ph: 575-748-4168

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 12 T17S R30E NENW 660FNL 1980FWL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other
Right of Way

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleting horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleting in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

EOG Y Resources, Inc. respectfully requests to install communications tower on Gissler 3-1 battery.
Tower Type 65 ft Tylon STG freestanding. 5.8 GHz 2.4 GHz unlicensed, 900 MHz.

The following wells are associated with this battery:

- Gissler B 14 30-015-22004 ✓
- Gissler B 27 30-015-25987 ✓
- Gissler B 28 30-015-25988 ✓
- Gissler B 52 30-015-37241 ✓
- Gissler B 53 30-015-37242 ✓
- Gissler B 59 30-015-37733 ✓
- Gissler B 62 30-015-40411 ✓
- Gissler B 64 30-015-38278 ✓

RECEIVED

OCT 17 2018

DISTRICT II-ARTESIA O.C.D.

OK Per Bud Ballard 10-15-2018 No New Disturbance All on file

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #434006 verified by the BLM Well Information System
For BURNETT OIL COMPANY INC, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 09/07/2018 (18PP2608SE)

Name (Printed/Typed) TINA HUERTA

Title REGULATORY SPECIALIST

Signature (Electronic Submission)

Date 09/05/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #434006 that would not fit on the form

32. Additional remarks, continued

Gissler B 65 30-015-37974 ✓
Gissler B 71 30-015-39210 ✓
Gissler B 75 30-015-39363 ✓