Submit 3 Copies To Appropriate District	State of Nove N	i.a.a	Farm C 102	
Office	State of frew Mexico		Form C-103 Revised March 25, 1999	
District I Energy, Minerals and Natural R		iturai Resources	WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-015-32508	
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1220 South St. Francis Dr.		ancis Dr.	STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM		VA-1691		
87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU-			7. Lease Name or Unit Agreement Name:	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Chimay BAO State	
PROPOSALS.)	139	101115/19/	Chimay BAO State	
1. Type of Well:	04har 🗖 (56)	1 To 1		
Oil Well Gas Well X Other				
2. Name of Operator	\sqrt{N}	1/2000	8. Well No.	
Yates Petroleum Corpor		ARTESIA	1	
3. Address of Operator		ARTESIA DO	9. Pool name or Wildcat	
105 S. 4 th Street Artesi	a, NM 88210	"I'ESIA ASI	Wildcat Atoka	
	\@ <u>`</u>			
4. Well Location				
Unit Letter <u>E: 1988</u> feet from the <u>North</u> line and <u>155</u> feet from the <u>West</u> line				
Section 2 Township 24S Range 23E NMPM Eddy County				
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4502' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	TENTION TO:	SUI	BSEQUENT REPORT OF:	
			LALTERING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO	CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DE	COMMENCE DRILLING OPNS. PLUG AND	
TEM CIVILLE ABANDON		ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A	AND -	
	COMPLETION	CEIVIEINT JOB		
OTHER:		OTHER: Perfora	ate and stimulate	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompilation.				
3/13/03 – Perforate Morrow 10,700'-10,704' (20).				
3/17/03 – Acidize Morrow with 1000g 7-1/2% HCL.				
3/20/03 – Set CIBP at 10,650'. Perforate Morrow 10,524'-10,536' (52).				
3/24/03 – Acidize Morrow with 1000g 7-1/2% Morrow acid.				
3/29/03 – Frac with 40# linear binary frac and 21,000# 18/64 Versaprop.				
4/1/03 – Set 5-1/2" composite plug at 10,512'. Perforate Morrow 10,434'-10,442' (36), 10,452'-10,458' (28),				
10,356'-10,362' (28) and 10,40		141011044 10,404 -1	0,442 (00), 10,402 -10,400 (20),	
4/3/03 – Acidize with 2500g 7-1/2% HCL & N2.				
4/10/03 - Relaize with 651 bbls foam frac and 50,000# 18/40 Versaprop.				
4/21/03 – Set composite plug at 10,335'. Perforate Atoka 10,240'-10,244' (25). TIH with 5-1/2 ASI packer and				
2.25 profile to 9994'.				
4/24/03 – Acidize Atoka with	1000a 7-1/2% AAS A			
		18/40 Versanson		
4/28/03 – Frac with 12,100g 65Q foam frac and 10,700# 18/40 Versaprop. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
I hereby certify that the information	above is true and complete to t	ne best of my knowle	edge and belief.	
SIGNATURE Juna Hunta TITLE Regulatory Compliance Supervisor DATE May 12, 2003				
Type or print name Tipa Huerta Telephone No. 505-748-1471				
	<u> </u>		Telephone No. 505-748-1471	
(This space for State who)				
APPPROVED BY Sim W. Seem TITLE District Segension DATE				
Conditions of approval, if any:			DAIL	