



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

31 March 2003

El Ran, Inc.

P. O. Box 911

Lubbock, Texas 79408



Form C-103 Report of Plugging for your Empire B. B. State # 1 O-16-19-31 API 30-015-25775  
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to  
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to  
indicate that the work has been accomplished and the location is ready for final inspection.

- Location OK*  
*OK For Recheck 6/6/03*
- ☒ 1. All pits have been filled and leveled.
  - ☒ 2. Rat hole and cellar have been filled and leveled.
  - ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
  - ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
  - ☒ 5. The dead men and tie downs have been cut and removed.
  - ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
  - ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Robert R. Ranch  
Name

Pres.  
Title


Van Barton  
Field Rep. II

Submit 3 Copies To Appropriate District Office  
District I  
 1625 N. French Dr., Hobbs, NM 88240  
District II  
 1301 W. Grand Ave., Artesia, NM 88210  
District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources  
**OIL CONSERVATION DIVISION**  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-103  
 Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		WELL API NO. <b>30-015-25775</b>
2. Name of Operator <b>El Ran, Inc.</b>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator <b>P.O. Box 911, Lubbock, Texas 79408</b>		6. State Oil & Gas Lease No. <b>V-4460</b>
4. Well Location Unit Letter <b>D</b> : <b>660</b> feet from the <b>South</b> line and <b>1980</b> feet from the <b>East</b> line Section <b>16</b> Township <b>19-S</b> Range <b>31-E</b> NMPM <b>Eddy</b> County		7. Lease Name or Unit Agreement Name: <b>B.B. State</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3531.4 GL</b>		8. Well No. <b>1</b>
		9. Pool name or Wildcat <b>Hackberry Delaware</b>



11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

02/03/03 Notified OCD. MIRU Triple N rig # 26 and plugging equipment. POOH w/ 178' 3/4" rods. NU BOP, POOH w/ 2-3/8" production tbg. RIH w/ 5 1/2" CIBP, SDFN.

02/04/03 Notified OCD. Continue in the hole w/ CIBP, set @ 4,520'. Circulated w/ mud. Pumped 60 sx C cmt @ 4,520'. POOH. RIH w/ wireline, CCL and weight bar in an attempt to find DV tool. Stacked out on cmt @ 3,891'. Did not locate DV tool. POOH. ND BOP and wellhead. Stretched 5 1/2" csg, indicates freepoint 379 - 343'. NU wellhead and BOP. RIH w/ tbg to 2,174'. Pumped 25 sx C cmt @ 2,174'. POOH, SDFN.

02/05/03 Notified OCD, Gerry Guye. RIH w/ tbg and tagged cmt @ 1,922'. PUH to 681'. Pumped 25 sx C cmt w/ 2% CaCl<sub>2</sub> @ 681'. POOH w/ tbg. WOC 3.0 hrs. RIH w/ wireline and tagged cmt @ 355'. PUH and perforated @ 60'. POOH. ND BOP. RIH w/ 1 joint and squeezed 25 sx C cmt 60' circulated to surface. RDMO to B.B. State #2.

02/18/03 Cut off wellhead and capped well, installed marker. Covered pit and cellar.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE Engineer DATE 2/28/03

Type or print name James F. Newman, P.E. Telephone No. 915-687-1994

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE JUN 12 2003

Conditions of approval, if any:

JUN 12 2003