

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.Serial No.
NMLC028793A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 27. If Unit or CA/Agreement, Name and/or No.
NMNM88525X

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other8. Well Name and No.
BURCH KEELY UNIT 967H2. Name of Operator
COG OPERATING LLCContact: SANDY BALLARD
E-Mail: sballard@concho.com9. API Well No.
30-015-39579-00-S13a. Address
600 W ILLINOIS AVENUE
MIDLAND, TX 797013b. Phone No. (include area code)
Ph: 432-686-437310. Field and Pool or Exploratory Area
BURCH KEELY-GLORIETA-UPR YES

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 19 T17S R30E NWSW 1728FSL 245FWL

11. County or Parish, State

EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Venting and/or Flaring
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Burch Keely Unit 967H
Burch Keely Sat. A Battery
Permit approval: Electronic Submission #408397
Actual gas flared for this battery for 7/2/2018 TO 9/30/2018 is as follows:

July
Total for Battery = 0 MCF
Aug
Total for Battery = 0 MCF
Sept
Total for Battery = 1708 mcf

Number of wells to flare: (47)

NM OIL CONSERVATION
ARTESIA DISTRICT

DEC 12 2018

Accepted for record

NMOC

RECEIVED

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #445470 verified by the BLM Well Information System

For COG OPERATING LLC, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 12/06/2018 (19PP0512SE)

Name (Printed/Typed) SANDY BALLARD

Title SENIOR ADMINISTRATIVE ASSISTANT

Signature (Electronic Submission)

Date 11/28/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

DEC 06 2018

/s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #445470 that would not fit on the form

32. Additional remarks, continued

BURCH-KEELY UNIT 85 30-015-21663 ✓
BURCH-KEELY UNIT 87 30-015-21662 ✓
BURCH-KEELY UNIT 88 30-015-21665 ✓
BURCH-KEELY UNIT 89 30-015-03079 ✓
BURCH-KEELY UNIT 90 30-015-03073 ✓
BURCH-KEELY UNIT 106 30-015-26890 ✓
BURCH-KEELY UNIT 107 30-015-03076 ✓
BURCH-KEELY UNIT 108 30-015-25668 ✓
BURCH-KEELY UNIT 110 30-015-03067 ✓
BURCH-KEELY UNIT 139 30-015-03102 ✓
BURCH-KEELY UNIT 141 30-015-03110 ✓
BURCH-KEELY UNIT 219 30-015-27726 ✓
BURCH-KEELY UNIT 220 30-015-27769 ✓
BURCH-KEELY UNIT 221 30-015-27764 ✓
BURCH-KEELY UNIT 222 30-015-27788 ✓
BURCH-KEELY UNIT 235 30-015-28584 ✓
BURCH-KEELY UNIT 245 30-015-28156 ✓
BURCH-KEELY UNIT 246 30-015-28330 ✓
BURCH-KEELY UNIT 247 30-015-28335 ✓
BURCH-KEELY UNIT 271 30-015-29301 ✓
BURCH-KEELY UNIT 276 30-015-29512 ✓
BURCH-KEELY UNIT 280 30-015-29921 ✓
BURCH-KEELY UNIT 281 30-015-29511 ✓
BURCH-KEELY UNIT 282 30-015-29722 ✓
BURCH-KEELY UNIT 314 30-015-31526 ✓
BURCH-KEELY UNIT 315 30-015-30642 ✓
BURCH-KEELY UNIT 324 30-015-32427 ✓
BURCH-KEELY UNIT 325 30-015-32428 ✓
BURCH-KEELY UNIT 326 30-015-32429 ✓
BURCH-KEELY UNIT 340 30-015-32757 ✓
BURCH-KEELY UNIT 344 30-015-32712 ✓
BURCH-KEELY UNIT 345 30-015-32713 ✓
BURCH-KEELY UNIT 363 30-015-32992 ✓
BURCH-KEELY UNIT 365 30-015-32867 ✓
BURCH-KEELY UNIT 376 30-015-33569 ✓
BURCH-KEELY UNIT 413 30-015-36209 ✓
BURCH-KEELY UNIT 415 30-015-37131 ✓
BURCH-KEELY UNIT 623 30-015-38561 ✓
BURCH-KEELY UNIT 624 30-015-39126 ✓
BURCH-KEELY UNIT 629 30-015-40705 ✓
BURCH-KEELY UNIT 630 30-015-38647 ✓
BURCH-KEELY UNIT 631 30-015-38648 ✓
BURCH-KEELY UNIT 636 30-015-38558 ✓
BURCH-KEELY UNIT 637 30-015-40183 ✓
BURCH-KEELY UNIT 699 30-015-39551 ✓
BURCH-KEELY UNIT 966H 30-015-44067 ✓
BURCH-KEELY UNIT 967H 30-015-39579 ✓

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT DUE TO HLP OR PLANT MAINTENANCE