FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WEDSICH FIELD OF MACCO28731B

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

UNITED STATES

DEPARTMENT OF THE INTERIOR

6. If Indian, Allottee or Tribe Name Artesia

SUBMIT IN TRIPLICAT	7. If Unit or CA/Agreement, Name and/or No. NMNM111789X			
1. Type of Well Gas Well Other		8. Well Name and No. DODD FEDERAL UNIT 918H		
Name of Operator Contact: SANDY BALLARD COG OPERATING LLC E-Mail: sballard@concho.com		9. API Well No. 30-015-42940-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-686-4373	10. Field and Pool or Exploratory Area DODD-GLORIETA-UPPER YESO		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State		
Sec 15 T17S R29E SENE 1650FNL 190 32.837192 N Lat, 104.054161 W Lon	FEL	EDDY COUNTY, NM		

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	🗖 Acidize	🗖 Deepen	Production (Start/Resume)	U Water Shut-Off		
Subsequent Report	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity		
	🗖 Casing Repair	New Construction	Recomplete	Other		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	Venting and/or Flari ng		
	Convert to Injection	Plug Back	Water Disposal	0		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Dodd Federal Unit 918H Dodd Federal Unit 10B Battery Permit approval: Electronic Submission # 412208 Actual gas flared for this battery for 4/24/2018 TO 7/23/2018 is as follows: April Total for Battery = 536 MCF May Total for Battery = 0 MCF June Total for Battery = 0 MCF Julv

Total for Battery = 0 MCF

RECEIVED

Accepted for record JAN 1 0 2019 DISTRICT II-ARTESIA O.C.D.

14. I hereby certify that t	he foregoing is true and correct. Electronic Submission #446514 verifie For COG OPERATING LI Committed to AFMSS for processing by PRI	.C, sen	t to the Carlsbad	4SE)			
Name (Printed/Typed)	SANDY BALLARD	Title	Title SENIOR ADMINISTATIVE ASSISTANT				
Signature	(Electronic Submission)	Date	12/05/2018				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By		Title	CEPTED FULL MILLO	<u> </u>	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	DEC 1 2 2018	/s/ Jonath	on Shepard		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its juristication of the United States any false, fictitious or fraudulent statements or representations as to any matter within its juristication. F 1 ANT 5 for the United States and St							
(Instructions on page 2)		1	CARESBAD HER UNITE	1	_		

** BLM REVISED **

Additional data for EC transaction #446514 that would not fit on the form

32. Additional remarks, continued

Number of wells to flare: (33) DODD FEDERAL UNIT 107 30-015-34564-00-S1 DODD FEDERAL UNIT 114 30-015-35622-00-S1 DODD FEDERAL UNIT 131 30-015-36731-00-S1 DODD FEDERAL UNIT 557 30-015-40597-00-DODD FEDERAL UNIT 558 30-015-39694-00-S01 DODD FEDERAL UNIT 558 30-015-39597-00-DODD FEDERAL UNIT 561 30-015-39598-00-DODD FEDERAL UNIT 563 30-015-39599-00-S01 DODD FEDERAL UNIT 565 30-015-39600-00-DODD FEDERAL UNIT 566 30-015-39695-00-DODD FEDERAL UNIT 576 30-015-39337-00-DODD FEDERAL UNIT 577 30-015-40000-00-DODD FEDERAL UNIT 579 30-015-39277-00- ~ DODD FEDERAL UNIT 580 30-015-39278-00-DODD FEDERAL UNIT 583 30-015-39602-00-DODD FEDERAL UNIT 585 30-015-39772-00-S01 --DODD FEDERAL UNIT 594 30-015-40001-00- -DODD FEDERAL UNIT 595 30-015-39279-00-S01-DODD FEDERAL UNIT 597 30-015-39664-00- -DODD FEDERAL UNIT 599 30-015-40453-00- -DODD FEDERAL UNIT 599 30-015-40454-00-S01 DODD FEDERAL UNIT 601 30-015-39605-00- > DODD FEDERAL UNIT 605 30-015-39280-00-DODD FEDERAL UNIT 606 30-015-39280-00-DODD FEDERAL UNIT 607 30-015-39281-00-DODD FEDERAL UNIT 609 30-015-40892-00-DODD FEDERAL UNIT 916H 30-015-40634-00- -DODD FEDERAL UNIT 917H 30-015-44128-00-DODD FEDERAL UNIT 918H 30-015-42940-00-Reason for flare: PLANNED MIDSTREAM CURTAILMENT DUE TO PLANT MAINTENANCE OR HLP