# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**OCD** Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


5. Lease Serial No. NMLC029392B

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

					_				
SUBMIT IN 1	7. If Unit or CA/Agree	ement, Name and/or No.							
1. Type of Well Gas Well Oth	8. Well Name and No. PRINCIPLE FEDERAL 1								
Name of Operator     CHEVRON USA INCORPORA	Contact: ATED E-Mail: howie.luca	HOWIE LUC s@chevron.co	AS n		9. API Well No. 30-015-32616-00-S1				
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone No Ph: 832-58	. (include area co 8-4044	ode)	10. Field and Pool or SHUGART	Exploratory Area			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	)			11. County or Parish,	State			
Sec 27 T18S R31E NENW 99	OFNL 1650FWL				EDDY COUNTY, NM				
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICA	TE NATURE	OF NOTICE	E, REPORT, OR OT	HER DATA			
TYPE OF SUBMISSION			ТҮРЕ	OF ACTION					
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Produ	ction (Start/Resume)	☐ Water Shut-Off			
M Notice of filterit	Alter Casing	☐ Hyd	raulic Fracturii	ng 🔲 Reclai	nation	■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	☐ Nev	Construction	☐ Recon	nplete	□ Other			
☐ Final Abandonment Notice	□ Change Plans	🛭 Plug	and Abandon	☐ Tempo	orarily Abandon				
	Convert to Injection	Plug	Back	□ Water	er Disposal				
If the proposal is to deepen directional Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fill 8 5/8" 32# 664' TOC surface, surfac	k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection.  5 1/2" 17# @ 6395' TOC to abandon this well as fortarting work (575) 234-59 est tubing t/ 1000 psi f/ 10 ts w/ BLM and engineer. The apply agreed upon by Cheng t/ 1000 psi f/ 10 min, so asing passed pressure to 50' t/ 4441' (Brushy Cany 200' t/ 1842' (Yates, B.Salt)	the Bond No. or sults in a multipled only after all 1870' via tem ollows: 909. 0 min, POOH Chevron plar evron and the poor of	in file with BLM/ e completion or requirements, incompletion or requirements, incomplete and the state of the	BIA. Required serecompletion in a cluding reclamate fis 6120'-6194 feed for recompletion in the series of the seri	ubsequent reports must be a new interval, a Form 316 ion, have been completed in the second s	HECEIVED  JAN 1 0 2019			
, , ,	Electronic Submission # For CHEVRON U tted to AFMSS for process	JSA INCORPO	RATED, sent	to the Carlsba	d				
Name (Printed/Typed) HOWIE LU	JCAS		Title ENG	INEER					
Signature (Electronic S	tubmission) THIS SPACE FO	OR FEDERA		4/2018 <b>E OFFICE I</b>	JSE				
					<del>-</del>				
Approved By	a amo	?	Title .	SAET		12-18-18 Date			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Office	C+0					
Title 18 U.S.C. Section 1001 and Title 43 States any talse, fictitious or fraudulent s					nake to any department or	agency of the United			

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



### Additional data for EC transaction #446496 that would not fit on the form

#### 32. Additional remarks, continued

6. Perforate casing at 714' and squeeze 170 sx CL "C" cmt f/ Surface t/ 714' (Shoe, FW, Surf).6. Cut off wellhead 3' below grade, Verify Cement To Surface, install required dry hole marker as per COA's, turn over to reclamation.

All cement plugs will be class "C" with a closed loop system used.

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

Well: Principle F 1 Field: Shugart Reservoir: Brushy Canyon

#### Current Wellbore Diagram

Location: Section: 27 Township: 18 Range: 31 County: Eddy State: NM

Well ID Info: Chevno: HJ8679 API No:3001532616 Spud Date: 2/28/2003 Compl. Date: 4/1/03

	TD, ft
Formation	Тор
Base of Salt	1,980
Yates	2,550
Queen	3,300
Delaware	4,600
Brushy Canyon	5,200
Bana Sasing	6.250

History:

-Significant paraffin Issues noted during each workover/pull job. The rods were stuck every job and required the use of (PAO3085) paraffin

Surface Csg: 8.625" 32#, unk Set: @ 664' Hole Size: 12.25" 17.5 Circ: Yes TOC: Surface TOC By: Circulated

Prod. Csg: 5 1/2", 17#, unk
Set: @ 6395'
Hole Size: 7 7/8"
Circ: No TOC: 1870
TOC By: Temperature Survey

Brushy Perfs @ 6120'-6194' -

11 1	1 1			ng Strings Description		25.00	ed Run?	1	<del></del> :	San Da	epin (415) (6KS	2	Sel Depth (TV	27112	<b>(5</b> )
	1	$\mathbb{R}^n$	Tubin			N.				6,41		•		-,,,,,	
	1 1	13	Runde	<b>a</b>		Run 3	œ			<b>30.0</b>	Ei <del>d</del>		PUE 300		
	1 1	-	5/7/2013			Drill and Suspend, 2/27/2003 00:00									
11 1		4	.73	nen Des	00	(tn)	1D (tr)	NA (CDS	G	906	Top Trreso	<b>Len (리)</b>	Tap (1)/05		5771 (EXE)
			193	TBG 6.5# J- 55	2	7/8		6.50	J-55	5		6,233.9 0	10	5.0	6,250.
			1	TAC 2 7/8 X 5 1/2	2	7/8				<u></u>		2.70	6,25	0.0	6,252.
		7	3	TBG 6.5# J- 55	2	7/8		6.50	) J-5!	5		81.95	6,25	2.7	6,314
			2	TBG 6,5# J- 55 TK-99	2	7/8		6.5	J-54	5		64.20	6,31	4.6	6,378
1 1	1 1		ļ		1	- 1		l	1		1	1			
	11		1	CUP SN	2	7/8	-		†			1.10	6,37	8.8	6,379
			1	SLOTTED MJ	2	7/8						31.60	6,37	9.9	6,411
			1	BULL PLUG	2	7/8			1			0.60	6,41	1.5	6,412
				sorpzon Detail	<u> </u>	Ptare	ed Run?	<del></del>		5±104	epta (*.45)	<u> </u>	SECEPTIV	D) (E	69
			Run 3a 5/10/	te		Run J	300			200			≥00 100		
	1 1	1	Rod	Components											
{·		}	m	nem d				(M) C	Grade		14 33E	Een (S	) Top (S	(3)	5m (8/2
	1 1		1	HF				1 1/2 F	R			26	.00	0.0	26
			98	NORRIS				7/8	1-90			2,450	.00 2	6.0	2,476
			146	NORRIS				3/4	1- <del>9</del> 0			3,650	.00 2,47	6.0	6,126
			8	NORRIS				1 1/2				200	0.00 : 6,12	6.0	6,326
			1	NORRIS GUI	DEC	RO	D	7/8	1-90			4	.00 6,32		6,330
<u>#</u> _	_ ‡	<del> </del>	4	PUMP				1 1/4				20	00 6,33	 ທຸກ	6,350

TD: 6395'

Anhy 640 T/Solf 675 B/salf 1980

Yetes 2550 Qu 3300 Pel 4600 Brushy Szov

Principle Fed 1 WBD.xlsm 4250

Well: Principle F 1
Field: Shugart
Reservoir: Brushy Canyon

Location	on:	
Section: 27 Township: 18		
Range: 31	State: NM	

Well ID Into:
Chevno: HJ8679
API No:3001532616
Spud Date: 2/28/2003
Compl. Date: 4/1/03

	TD, ft
Formation	Тор
Base of Salt	1,980
Yates	2,550
Queen	3,300
Delaware	4,600
Brushy Canyon	5,200
Bone Spring	6,250

#### History:


-Significant paraffin issues noted during each workover/pull job. The rods were stuck every job and required the use of (PAO3085) paraffin

Surface Csg: 8.625" 32#, unk Set: @ 664' Hole Size: 12.25" Circ: Yes TOC: Surface TOC By: Circulated

Prod. Csg: 5 1/2", 17#, unk Set: @ 6395' Hole Size: 7 7/8" Circ: No TOC: 1870 TOC By: Temperature Survey

Brushy Perfs @ 6120'-6194'

### Proposed Wellbore Diagram



Principle Fed 1 WBD.xlsm 12/4/2018 2:43 PM