

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON OIL CONSERVATION (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-64315
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ARMSTRONG ENERGY CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1973, Roswell, NM 88202-1973		7. Lease Name or Unit Agreement Name Huckleberry State
4. Well Location Unit Letter <u>J</u> : <u>2402</u> feet from the <u>South</u> line and <u>1610</u> feet from the <u>East</u> line Section <u>10</u> Township <u>15S</u> Range <u>28E</u> NMPM Chaves County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 1092
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: Perf & Acidize ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/19/18 RU WL. TIH, tie in and set CIBP @ 7875', w/two 40' bailers of cement. TIH, tie-in and perforate 7726'-7735', 20 holes; 7764'-7772', 18 holes; 7786'-7794', 18 holes; and 7803'-7812', 20 holes. RD WL. TIH w/pkr & tbg. SISD.
12/20/18 SITP 0 psi. RU swab. Tag fluid @ 1900'. Made 13 runs and rec 110 BW. Last run 3%-4% oil cut.
12/21/18 RU swab. Made 13 runs, rec 110BW.
12/22-12/25 SD
12/26/18 RU swab, made 2 runs, slight gas & oil cut on first run. Rec 10 BW. Release pkr, TOH w/tubing, LD pkr, TIH w/234 jts 2 7/8" tbg, open ended. ND BOP, flange up tree. RDPU. Prep to plug.

Spud Date:

08/30/2018

Rig Release Date:

09/20/2018

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kyle Alpers TITLE VP - Engineering DATE 1/9/19

Type or print name Kyle Alpers E-mail address: kalpers@aecnm.com PHONE: 575-625-2222

APPROVED BY: Rusty Kline TITLE Business Ops Spec DATE 1-9-2019

Conditions of Approval (if any):