Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF L'AND MANAGEMENT

Operator

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	Expires:	January 3
Lease	Serial No.	

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					Lease Serial No.     NMLC068282B     If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well  ⊠ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. GOLDEN SPUR 25 FBS 3H			
2. Name of Operator Contact: GREG BRYANT CONOCOPHILLIPS COMPANY E-Mail: GREG.BRYANT@BASICENERGYS				S.COM	9. API Well No. 30-015-41230-00-S1			
3a. Address HOUSTON, TX 77252	3b. Phone No. (include area code) Ph: 432-563-3355 Fx: 432-563-3364			10. Field and Pool or Exploratory Area WC 015 G 05 S263125N				
4. Location of Well (Footage, Sec., T Sec 25 T26S R31E SWSW 46	TO INDICATE NATURE OF NOTICE			11. County or Parish, State EDDY COUNTY, NM				
		<u> </u>						
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE	NATUREO	F NOTICE,	REPORT, OR OTH	EER DATA		
TYPE OF SUBMISSION		. Ri	TYPE OF	ACTION				
☐ Notice of Intent	☐ Acidize	☐ Deeper	□ Deepen □ Production (Start/Resume		on (Start/Resume)	☐ Water Shu	t-Off	
	☐ Alter Casing		lic Fracturing	☐ Reclama		☐ Well Integ	rity	
Subsequent Report	Casing Repair		onstruction		decomplete			
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	Plug an	Plug and Abandon					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  2/8/19 - MIRU, open well 0 psi 2/11/19 - RIH 201 jts tbg 2/12/19 - Con't RIH Tbg, Tag BP @ 8500'. Circ hole w/ MLF. Pressure test csg to 500#, held. Spot 45sx cmit @ 6964' Tag @ 6450'. Spot 25sx cmt @ 5126' 2/13/19 - Spot 30sx cmt @ 4191'' Tag @ 3901'. Perf @ 2801' - Sqz 40sx cmt 2/13/19 - Tag @ 2600'. Perf @ 1187' - Sqz 150sx cmt - Tag @ 800'. Perf @ 60' - Circ 80sx cmt to  Surface 2/15/19 - Verify cmt @ surface. RDMO  RECLAMATION DUE 8-14-19'								
14. I hereby certify that the foregoing is  Comm  Name (Printed/Typed) GREG BR	455081 verified be HILLIPS COMPA sing by DEBORA	NY. sent to th	e Carlsbad on 02/19/201	•				
The state of the s				· · · · · ·			-	
Signature (Electronic Submission)			ate 02/19/20	019	ACCEPTED	FOR RECO	)PD	
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE US	SE T			
Approved By		Title		FEB	9 2019			
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	e subject lease	Office		BUREAU OF LAND MANAGEMENT				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any perso to any matter withi	n knowingly and n its jurisdiction.	willfully to ma	ke to any department or	ragency OFFICE mi	ted	

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

X7 NMOCD 2-25-19



## United States Department of the Interior

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612